



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060256/Unh3
16 RAFFLES QUAY	Date:	26/06/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 449D	Veh. Inspected	SLX 2142S
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005570MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	26/06/2024

2. Vehicle Details

Make & Model	NISSAN SYLPHY (A)	C.C	1598
Engine No.	HR16947727B	Year of Reg.	06/09/2014
Chassis No.	MNTBBAB17Z0020013	Colour	GREY
Odometer	238109 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45ZR17	HABILEAD	6
L/H Front Tyre	225/45ZR17	HABILEAD	6
R/H Rear Tyre	225/45ZR17	ARIVO	4
L/H Rear Tyre	225/45ZR17	ARIVO	4

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2024	Inspection Date	26/06/2024
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days