

REF: CS/LAW24110127/Anp3 (GBC 8781L)

Special Instruction:

L/SUM: 6700 / REPAIR: 6 WORKING DAYS

Third Parties:

Claimant: ~~IMPACT ANALYSIS~~

Surveyor: IMPACT AND
CONSULTING

Workshop: ECO AUTOMOBILES

ASSIGNMENT (Office)

From (Person): VITHY of KELVIN CHIA PARTNERSHIP Date/Time: 04/11/2024
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBC 8781L Insured: GBG 2749A

at Workshop m/s ECO AUTOMOBILES

of 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY

Policy No: _____ Claim No: NR/2023001190

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/03/2021
(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 10/05/25 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original ____ days)

Date/Time: 19/05/25 Submit Final Fig 1068, 1 days (Red \$5632 / 84%; Original 6 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

Date/Time		File Pass to		File Return to		Total
1)	Date/Time		File Pass to	2)	Date/Time	File Return to
3)	Date/Time		File Pass to	4)	Date/Time	File Return to
5)	Date/Time		File Pass to	6)	Date/Time	File Return to