

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24110135/Uqh3e2	
	75 BRAS BASAH R	OAD SINGAPORE 189557	Date:	11/12/2024	
	INCOME CENTRE	SINGAPORE 109557	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLT 1045S	Veh. Inspected	JVH 4615	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1295684-002	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	07/11/2024	
2.					
	Make & Model	MODENAS KRISS MJ110H	C.C	107	
	Engine No.	MJ110FELB5496	Year of Reg.	31/05/2022	
	Chassis No.	PMNMJ110HNML29697	Colour	BLUE	
	Odometer	66649 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	70-90-17	MAXXIS	6	
	L/H Front Tyre				
	R/H Rear Tyre	80-90-17	MAXXIS	6	
	L/H Rear Tyre				
4.	Description of Damages				
THE	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.					
5.		General Information			
	Accident Date	17/09/2024	Inspection Date	08/11/2024 (10:10)	
		Survey held at EROFIA MOTOR TRADING PTE LTD			
	Survey held at				
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62			
	Survey held at	1 KAKI BUKIT AVENUE 6			
5a.	·	1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883	arks		
A) T	HE INSPECTION W	1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883	arks EJUDICE" BASIS.	DEDAIRS	

Estimate Days of Repair