



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24110140/Anh3m4(N)

Date: 28/07/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 5468R	Veh. Inspected	GBD 1223Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1301951-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	07/11/2024

2. Vehicle Particulars & Condition

Make & Model	mitsubishi canter	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	FEA01BA00304	Colour	WHITE
Odometer	343263 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/75 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/75 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/10/2024	Inspect Date / Time	12/11/2024 (11:23 AM)
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**