

TSR AUTOMOTIVE PTE LTD

HANDPHONE 90030857

Date : 7 Nov 2024

QUOTATION - THIRD PARTY CLAIM

M/S FIRST CAPITAL INSURANCE

Not Authorized
11/11/24 8:30 AM

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 4 Nov 2024 *Return After Repair*

VEH. No : FBL 5460 K / YAMAHA

ATTN : MOTOR CLAIM DEPARTMENT

1 day

INSURE : INCOME

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SHA 8771 E			
1	FRONT HANDLE BAR	\$ <i>2</i> 380.00	X
1	FRONT BALANCER RH	\$ <i>2</i> 285.00	X
1	FUEL TANK ASSY	\$ <i>2</i> 650.00	X
1	FRONT BRAKE DISC	\$ <i>2</i> 385.00	X
1	FRONT BRAKE	\$ <i>2</i> 280.00	X
1	FRONT FORK	\$ <i>2</i> 1,120.00	X
1	FRONT BRAKE LEVER	\$ <i>2</i> 298.00	X
	TOTAL PARTS :	\$ 3,398.00	
	LESS 10%	\$ 339.80	
	TOTAL LIST PARTS :	\$ 3,058.20	
	<u>S/NETT PARTS</u>		
1	FRONT LOWER IRON SUPPORT	\$ <i>2</i> 500.00	<i>320.00</i>
	TOTAL S/N :	\$ 500.00	
	TOTAL PARTS PRICE :	\$ 3,558.20	
AMOUNT BRING FORWARD :		\$ 3,558.20	
Labour charge s	<i>50%</i>	\$ 500.00	
Anti rust		\$ <i>2</i> 120.00	X
Check wiring system .		\$ <i>2</i> 120.00	X
To do spray painting on accident area		\$ <i>2</i> 300.00	X
	TOTAL LABOUR :	\$ 1,040.00	
	GRAND TOTAL PARTS & LABOUR :	\$ 4,598.20	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR :