



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24110169/Anh3e2

Date: 24/02/2026

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMN 9770Z	Veh. Inspected	SLJ 5211E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302183-002	Excess (\$)	0.00
Assign From	ANNA YEO	Assign Date	08/11/2024

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFEAJ11U1709291	Colour	BROWN
Odometer	363469 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2024	Inspect Date / Time	26/11/2024 (01:52 PM)
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**