

REF: CS/LIP 24/10/75/Kgh3

C

ASS. REC. BY:

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Accord

of 0686

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$53K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBK 8237M Regn: 09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or NA

Make: NIP NV200 c.c. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 124588 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1YAA M 208 0001158

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 175/70R14

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 8 mm Rear R/Bal. 7 mm

L/Bal. 8 mm L/Bal. 7 mm

D.O.A. 8/11/24 D.O.I. 8/11/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or O/S in QULC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>22/11</u>	<u>LIP @ 3300. Cabot</u>
<u>10/12/24</u>	<u>@ 2130 re-finalized with Jacqueline LS @ 3150, 5 days. (Red # 734508, 70%)</u>

Date/Time, File Pass to?  : Prell. Report  : Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:	
Transportation	
S - RS. SI	
Fuel	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ )  : Interview (\$ )  : Tech Invs (\$ )  : Weekend (\$ )

Report Format: TP  
Lump Sum / I.B.A. (\$): 3150

## Shiau Chan (LKKAUTO)

---

**From:** Nguyen, Duc Thinh <DucThinh.Nguyen@libertyinsurance.com.vn>  
**Sent:** Tuesday, 26 November 2024 4:02 PM  
**To:** Shiau Chan (LKKAUTO)  
**Cc:** Report; Seah, Andy; SUR  
**Subject:** RE: SURVEY ASSIGNMENT FOR 09/11/2024

Dear Shiau Chan,

As indicated in the initial marking, please:

*P103098*

1. Provide more damage photos of FRONT RH SIDE PANEL (#1), TYRE (SUPP #3) (cannot see damage).
2. Negotiate to repair FRONT FENDER (slightly bent).

*P103097*

Thank you,

**Best regards,**

**Nguyen Duc Thinh**

Claims - Motor

Mobile/WhatsApp: +84 909 232 062

---

**From:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Sent:** Tuesday, November 26, 2024 2:16 PM  
**To:** Nguyen, Duc Thinh <DucThinh.Nguyen@libertyinsurance.com.vn>  
**Cc:** Report <report@lkkauto.com>; Seah, Andy <Seah.Andy@libertyinsurance.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** {EXTERNAL} RE: SURVEY ASSIGNMENT FOR 09/11/2024

Dear Thinh,

Enclosed herewith 2<sup>nd</sup> preliminary advice of GBK 6237M

For your approval.

Best Regards,

**Shiau Chan (Ms)** | Senior Case Handler

Own Damage & Third Party Property Damage

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nguyen, Duc Thinh <DucThinh.Nguyen@libertyinsurance.com.vn>  
**Sent:** Tuesday, 26 November 2024 12:31 PM  
**To:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Cc:** Report <report@lkkauto.com>; Seah, Andy <Seah.Andy@libertyinsurance.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSIGNMENT FOR 09/11/2024



# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

3RD PARTY

**LIBERTY INSURANCE PTE LTD**  
ATTN: ACCIDENT CLAIMS DEPARTMENT

FIRST REGISTRATION: 26.09.2020

DATE : 08.11.2024  
VEHICLE NO : GBK6237M  
VEH MAKE/MODEL : NISSAN NV200  
YOM : 2020  
CHASSIS NO : JN1YAAM20Z0001158  
DATE OF ACCIDENT : 06.11.2024

		<u>SPECIAL NETT ITEMS:-</u>			
1	SET	FRONT BUMPER CLIPS	\$ 20	Ma	50.00
2	SET	FRONT FENDER INNER SHIELD RH <i>clips</i>	\$ 20	Ma	50.00
3	1	TYRE <i>2006N</i>	\$	Pin	<del>380.00</del> 150
4					
5					
6					
<b>Total - SN Item</b>			<b>\$</b>		<b>450.00</b>
		<u>Labour Charges:-</u>			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$		1,000.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$		1,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$		100.00
		TO APPLY ANTI RUST TREATMENT	\$		120.00
4		TO REMOVE/REPLACE/REFIX/ FRONT RH & TYRE & RIM, UNDERCARRIAGE REPLACEMENT	\$		380.00
5		TO CHECK & ADJUST WHEEL ALIGNMNET	\$		100.00
6					
7					
<b>Total - L/C</b>			<b>\$</b>		<b>2,700.00</b>
<b>Sub-Total</b>			<b>\$</b>		<b>10,495.08</b>
<b>9% GST</b>			<b>\$</b>		<b>944.56</b>
<b>Total</b>			<b>\$</b>		<b>11,439.64</b>

*809m*

*350d  
500d  
2d  
3d X  
200d  
60d X*