



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24110175/Kqh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	16/12/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 3109Y	Veh. Inspected	GBK 6237M
Policy No.	-	Coverage	0
Claim No.	DVS24/0265	Excess	\$0.00
Assign From	CMPU	Assign Date	08/11/2024

2. Vehicle Details

Make & Model	NISSAN NV200 1.6 (A)	C.C	1598
Engine No.	HR16171171D	Year of Reg.	26/09/2020
Chassis No.	JN1YAAM20Z0001158	Colour	WHITE
Odometer	124566 KM	Steering	JAMMED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70R14	DUNLOP	8
L/H Front Tyre	175/70R14	DUNLOP	8
R/H Rear Tyre	175/70R14	DUNLOP	7
L/H Rear Tyre	175/70R14	DUNLOP	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/11/2024	Inspection Date	08/11/2024
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days