

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/CTI 24110179/RVh302

9909

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMU 76904

at Workshop m/s PERFORMANCE

of ALEXANDRA RS RS

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10am

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

139K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 76904

Yr Regn:

2020 / 144

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 320I LEO HL

c.c 1958

Colour

WHITE

AC: Insured / Std / NI / NA

Sp. Reading

54535

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA JF 320 70F H84 693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/35R19

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

06/11/24

D.O.I.

03/12/24

Survey held at

ALEXANDRA

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REGAM LIM G - 74K

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

⇒ China

ESTIMATE

14 Nov 2024

Estimate No. : b1 71805
Date Estimated : 14/11/2024
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Seow Khim Chuang (Xiao Jinchuan)
Blk 10 Pari Dedap Walk
#09-21

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 486062

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU7690Y	WBA5F32070FH84693	28/08/2020	320i Sedan	52567

DESCRIPTION

VALUE

To replace front bumper, right front fender and all damage attachment

1700 2,500.00

To respray front bumper and right front fender

1,923.00

To carry out body cavity preservation.
(Per panel).

118.00

To check electrical wiring

177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

177.00

To replace right headlight.

481.00

Sundries.

150.00

Total Labour 1: 5,576.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SIDE PANEL BRACKET 3 ?	1	64.95	64.95
FRT RH SIDE PANEL BRACKET 1 ?	1	64.95	64.95
FRT RH SIDE PANEL <i>repl</i> ?	1	887.15	887.15
FRT SHOCK ABSORBER ?	1	99.50	99.50
FRT BOTTOM IMPACT ABSORBER ?	1	71.10	71.10
FRT BUMPER CARRIER ?	1	718.20	718.20
RH SUPPORT ?	1	156.90	156.90
FRT BUMPER PANEL PRIMED (M/PDC/PMA) <i>cm</i>	1	1,394.55	1,394.55
RH HEADLIGHT LED AHL <i>sm</i>	1	3,755.35	3,755.35

Total Parts : 7,212.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 71805
Date Estimated : 14/11/2024
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU7690Y	WBA5F32070FH84693	28/08/2020	320i Sedan	52567

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 02/12/24 Excess S\$ _____Surveyor's Name Rasul Sign _____Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

Res by part



Labour 1	:	5,576.00
Parts	:	7,212.65
Labour 2	:	0.00
Excess	:	0.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	07/11/2024 16:12 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	06/11/2024 22:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	NICOLL HIGHWAY TOWARDS SUNTEC CITY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMU7690Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SEOW KHIM CHUANG (XIAO JINCHUAN)
NRIC No	S7724990G
Email Address	STANSEOW@YAHOO.COM
Mobile Phone No	(Phone) +65-96495036
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	320i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000
Vehicle Fuel	Petrol
First Registration Date	28/08/2020
Chassis no	WBA5F32070FH84693
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10611420R03

DRIVER

Name of Driver
NRIC No
Date Of Birth
Occupation
Driving Pass Date
Driving License Pass Class
Driving License Validity
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

SEOW KHIM CHUANG (XIAO JINCHUAN)
S7724990G
17/08/1977
Indoor
12/02/1998
3
Valid
26 YEARS AND 9 MONTHS
Male
(Phone) +65-96495036
-
STANSEOW@YAHOO.COM
10 PARI DEDAP
#09-21
486062
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Cross Junction
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING HOME FROM UOB PLAZA. AT ESPLANADE DRIVE, I STOPPED AT THE TRAFFIC JUNCTION WHEN THE LIGHT WAS RED. THE MOMENT THE LIGHT TURNED GREEN, I GRADUALLY ACCELERATED. VEHICLE SML 6146 G TURNED LEFT INTO MY LANE FROM THE RIGHT LANE SUDDENLY. IT COLLIDED WITH MY VEHICLE. THE LANES ARE FOR DRIVING STRAIGHT. IT IS AN OFFENCE THAT SML 6146 G HAD COMMITTED, TRYING TO TURN LEFT INTO STAMFORD ROAD.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SML6146G

Honda

-

-

White

Private car

ROY S SELVARAJAN@SIRAAJ

(Phone) +65-97726477

-

-

-

-

-

-

-

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time


[Signature]

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan




Describe Circumstance of the Accident


I was driving home from UOB Plaza.. At esplanade drive, I stopped at the traffic junction when the light was red. The moment the light turned green, I gradually accelerated. Vehicle SML 6146G turned left into my lane from the right lane suddenly. It collided with my vehicle. The lanes are for driving straight. It is an offence that SML 6146G was ~~trying~~ had committed, trying to turn left into Stamford road.

Declaration


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	990G
Vehicle Details	
Vehicle No.:	SMU7690Y
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2024
Vehicle Make:	B.M.W.
Vehicle Model:	320I LED HL
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	F7023511B48B20A
Chassis No.:	WBA5F32070FH84693
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$46,843.00
Original Registration Date:	28 Aug 2020
First Registration Date:	28 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$57,581.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2030
PARF Rebate Amount:	\$43,185.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$36,502.00
COE Rebate Amount:	\$20,910.00
Total Rebate Amount:	\$64,095.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 04 Dec 2024

OK



BMW 3 Series 320i Highline

\$139,588 Instalment \$1,423/mth

Apply for 2.48% loan

Shortlist

Get Warranty

- Overview
- Financial
- Photo
- Research

Depreciation	<div></div> \$19,540 / year
Reg. Date	26-Aug-2020 (5yrs 8mths 21days COE left)
Manufactured	<div></div> 2019
Mileage	85,123 km (19.9k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	<div></div> \$1,210 / year
Power	135.0 kW (181 bhp) View specs of the BMW 3 Series Sedan (2019)
Curb Weight	<div></div> 1,460 kg
COE	<div></div> \$38,802
OMV	<div></div> \$45,247
ARF	<div></div> \$55,346
Dereg Value	<div></div> \$63,728 as of today
No. of Owners	<div></div> 1