SK0024600005 / KANG CAR REPAIRERS PTE LTD ENTRY DATE & TIME: 24/06/2024 16:08 (SGT) SUBMITTED BY: SHARON YEE VERSION: 1 (24/06/2024 16:08 (SGT))



# SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- In elissue and acceptance of this Form by insurance companies is not an admission of policy making of the part of the particle companies.
   Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
   By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of First Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

24/06/2024 16:08 (SGT) Both Policyholder and Actual Driver 22/06/2024 11:05 (SGT) Singapore EUNOS LINK / BEDOK RESERVOIR RD Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SMQ9094B

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No

Yes COMFORTDELGRO DRIVING CENTRE PTE LTD 1XXXXX882C DARYLTAN@CDC.COM.SG (Phone) +65-90072819

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

Employment

Toyota

Vios

No - Claiming third party

Private car Auto 1500

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

MS First Capital Insurance Ltd D-24101930MFQC/132

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

ATHAYA FADIYAH TXXXX631H 26/10/2015 Indoor



 Driving Pass Date
 22/06/2024

 Driving experience
 0 MONTH

 Gender
 Female

 Mobile Number
 (Phone) +65-85003511

Alt. Phone Number

Email Address DARYLTAN@CDC.COM.SG
Address 27 TAMPINES ST 86 #05-23
Address complement -

Postcode 528570
Is the driver the policyholder?
No

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Change/cross lane
Weather Conditions Raining
Road Surface Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

No
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Yes
Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No
Translator's name

Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement -

PASSENGER 1

Name KOI JOO GUAN Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 22/06/2024 AT 11,05AM, I WAS DRIVING AT EUNOS LINK AFTER JUNCTION OF BEDOK RESERVOIR RD WHEN A 3RD PARTY VEHICLE BEARING REGISTRATION NUMBER WD6337X SUDDENLY COLLIDED INTO THE SIDE OF MY VEHICLE . AFTER THE IMPACT, MY VEHICLE LOST CONTROL.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Yes

Yes

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number Vehicle Manufacturer

WD6337X

-



Vehicle Model Vehicle Variant Vehicle Colour

Vehicle Category Commercial vehicle Name of Driver

GURUNADHAN PILLAI RAMESH Contact Number (Phone) +65-98644693 Address

Address complement Postcode Insurance Company Name Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

VEHICLE B

# WITNESS DETAILS

WITNESS 1

Name KOI JOO GUAN Phone (Phone) +65-90088662 Email

## SKETCH PLAN

### IMPORTANT NOTICE

- 1. Rease report <u>correctly</u> the datails of the accident to speed up the claims process
- 2. This Formitrust be gomplated by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful insceptasentation or withholding of malerial facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of opticy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GM Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fige be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Cate Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer in my workshop and the General insurance Association of Singapore ("GIA") may fare permitted to collect, use, discloss and/or process my dersonal data/parsonal information set out in this [form] and any other personal information provided by me or coassessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurers with no have insured vehicle(s) involved in this accident (all insurer(s) wind have insured vehicle(s) involved in this accident shall be accident (all insurers) and personal information which accident shall be accidently referred to as the "insurers"; the insurers law yershaw firms the Monetary Authority of Singapore and any relevant government agency/authority (such as the disclose), for the purpose(s) of
- (f) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the socident and/or my cleims
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (br) administering my claims (including the mailing of correspondence, statements, invotes, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail cackages); and/or
- (v) complying with spolloable law in administering processing, handling and/or dealing with my claims, (collectively the 'Purposes')

CM Q90248-1

- (b) all insurer(s) who have insured vahiolo(s) involved in this socident and the insurers lawyers law firms imay/are dermitted to collect use disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law //rms), which may be sited outside of Singapore, for one or mare of the above Purposes.

Policyholders, Sphalure / Date &

Sketch Plan

Criver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Persondel

Bunos Link

Describe Circumstances of the Accident
On 22 follows (date) at 11-05 nm (fine). I was driving at Curos Link after junction of Bedor Reservor Rd (Josephin) Whyn a 3rd gady vehicle bearing registration number wip 6337 x sulferly collided into the side of my vehicle. After the impact, my vehicle
Curos Link after junction of Bedor Reservor Rd (Josephin) When a
3rd garly vehicle bearing registration number wo 6337 X Sulterly
colleded to to the side of my vehicle. After the impact, my vehicle
10st control.
NOTE PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 CAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER
YOUR OWN POLICY, PLEASE CHECK YOUR POLICY FOR MORE INFORMATION
Oadaretton