

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 11/11/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/11/2024

Vehicle No : GBJ-1221-X

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER <i>de</i>	760.00	✓
1	FRONT BUMPER BRACKET LH <i>4</i>	280.00	✓
1	FRONT GRILLE <i>sa</i>	864.00	611
1	FRONT OUTER PANEL <i>lt</i>	1,150.00	1085
1	FRONT INNER PANEL <i>repar</i>		
1	FRONT CORNER PANEL LH <i>sa</i>	485.00	310
1	WING MIRROR (ROUND) LH <i>mls</i>	95.00	✓
1	HEADLAMP LH <i>bro</i>	670.00	569
1	SIGNAL LAMP LH <i>bni</i>	252.00	162

RESTORE

Date : 11/11/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/11/2024

Vehicle No : GBJ-1221-X

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
		RESTORE	
1	FRONT DOOR LH <i>repair</i>		
1	STEP PANEL GARNISH LH <i>cm</i>	4030	320.00 158
	Sub Total	159	4876.00
	Discount 15% On Parts	3425.50	(731.40)
<u>Special Nett Item</u>			
1	FRONT NUMBER PLATE <i>lt</i>		35.00
1	ADVERTISEMENT STICKER <i>re</i>	255	300.00 200
1	DOOR ROC STICKER <i>re</i>		20.00

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 11/11/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/11/2024

Vehicle No : GBJ-1221-X

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	355.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,000.00	800
	TO RESPRAY AFFECTED PORTION	1,000.00	800
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	RUST PROOFING	50.00	
	Sub Total	2080.00	

6,579.60

Remarks:

6 days - 4/5 / Reg after repair

SUB TOTAL

GST 9.0 % 592.16

TOTAL 7,171.76

Surveyor's name: Rasul - Hp 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 12/11/24

PAGE : 3

SUPPLEMENTARY

Item : MOTOR CAR

: SOMPO INSURANCE SINGAPORE PTE LTD.

Certificate No : 1

Accident Date : 06/11/2024

Vehicle No : GRI 1771 X

Make & Model : ISUZU NHR87A11AAA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>LIST ITEM</u>	COOLING COIL HOUSING (cra)	1,140.00	900
	Sub Total	1140.00	
	Discount 15% (On Works)	(171.00)	
	TO TOP UP AIRCON GAS	120.00	
	Sub Total	120.00	

Remarks:

SUB TOTAL

1,187.01

TOTAL

1,187.01

Signature of Surveyor

Principal's name: ETHOZ Group Ltd

Signature of Principal

PAID

P- 4190.50
S/W- 255.00
L- 1800.00
T- 6245.50
20%
4996.40
45- \$5000/16 days