

Your Ref: 23/23/24/VC00/411162

Date: 17<sup>th</sup> July 2024

Our Ref: CS1/LPM24060264/Evp3m4

**M/s Lonpac Insurance Bhd**

21st Flr, Bangunan Public Bank  
No. 6 Jalan Sultan Sulaiman  
50000 Kuala Lumpur, Malaysia  
(The Motor Claims Department)

Attn: Alexander Neo

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKT 6030M**  
**INSURED VEHICLE: BPM 6872**  
**ACCIDENT DATE: 02/11/2023**

We thank you for your instruction on 24/06/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKT 6030M from M/s T & C Automobile Assessors.
- b) Polis Diraja Malaysia of Vehicles SKT 6030M and BPM 6872.
- c) Colour damaged vehicle photographs of SKT 6030M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: SKT 6030M
Make & Model	: Nissan Sylphy 1.6 Cvt Abs D/Airbag 2WD 4DR
Chassis Number	: MNTBBAB17Z0022785
Year of Registration	: 2015
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.