

REF: CS1/LPM24060264/Evp3 (SKT 6030M)

Special Instruction:

L.SUM: 17000 / REPAIR: 17 DAYS

Third Parties:

Claimant:

Surveyor: T & C AUTOMOBILE ASSESSORS

Workshop: MING HUA AUTO SERVICES

ASSIGNMENT (Office)

From (Person): ALEXANDER NEO of LPM Date/Time: 24/06/2024
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKT 6030M Insured: BPM 6872

at Workshop m/s **MING HUA AUTO SERVICES**

of 160 SIN MING DRIVE #02-16 AUTOCITY

Policy No: _____ Claim No: 23/23/24/VC00/411162

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 02/11/2023

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red S ____ / ____ %; Original ____ days)

Date/Time: 27/6/24 Submit Final Fig LS \$5500, 8 days (Red \$ 11500 / 67 %; Original 17 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____