Asst. Sign: | REF:

ASSIGNMENT

From: _____ Date: _____

Estim. Cost: _____

OD / TPPD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O Workshop/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Veh No: SLR9329G Yr Regn: 2017, August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toyota Prius C.C 1797

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 580865 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVW40002606 3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: 205/60R16

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	12/11/24.

Survey held at NSI

Des. of Damages / Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC.
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes (✓) No ( )

Date/Time, File Pass to? 1) _____ ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ : Tech. Inv ($ _____)

Report Format : _____

Survey Fee: _____

Transportation: _____ $ + R$ _____ $

Photos _____

Others _____