

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estn: \_\_\_\_\_  
 OD / TP / RES / OD RES / EVA / INV / MV  
 To in \_\_\_\_\_ Vehicle NO: \_\_\_\_\_  
 at \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **SNB 2760A**  
 Policy No: \_\_\_\_\_  
 Claims No: **MT/1303397-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vch: \_\_\_\_\_  
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SMD4590L Yr Regn: 2018 August  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Elantra C.D. 1591  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 100801 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH D841cm JU 75455  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/40R18  
 R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. <u>8/11/2024</u>		D.O.I. <u>12/11/24</u>	

Survey held at: Advance  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP/INC</u>
<u>17/3/25</u>	<u>Adrian confirmed LS \$1100 (red 2443.28, 68%)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

COE Expiry: ✓  
 Estimate given during: Yes ( )  
 1st Survey: No ( ✓ )

592D

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Days Of Repair: 2  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invt (\$) \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + R.S. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_