Assg. By: REF:

ASSIGNMENT

From: Date:

Estim Dist:

OD / TPO / TP RES / OD RES / EVA / INV / MV

To in Vehicle No:

at WO Km/s

of

Insured:

Policy No

Claims No

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Veh No: SMD4590L Yr Regn: 2018, August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai Elantra C.C 1591

Colour Black. A/C: Insured / Std / NI / NA

Sp.Reading 100801 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHD841CnJU759455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18.

R: 225/40R18.

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	12/11/24.

Survey held at Advance.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC.
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes ( ) No (✓)

592D

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

☐ : ... ($)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format :

Preliminary / Final (S)