



53 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

**ESTIMATE** 

ACCIDENT REPAIRS

WORKSHOP

UBI ROAD 1 6366 2323

CONTACT NO

6841 1183

FAX NO REFERENCE

PAXP/TP/0003/2024/KS

DATE

18-Nov-24

WIP

10044

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY 19/11/2024

YOUR INSURED VEHICLE NO: SNF 7602 U

**LONPAC INSURANCE Bhd** 

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

**OWNER'S NAME** 

MR SOONG CHIN KHANG

**ADDRESS** 

27 FERNVALE ROAD

#22-27

SINGAPORE 797415

TELEPHONE

HP +65 97828858

TYPE OF CLAIM

THIRD PARTY CLAIM

POLICY NO

7240194396

VEHICLE NO

SNT 3410 J

MODEL CODE

XPENG G6 RWD (LONG RANGE)

**MODEL YEAR** 

26/9/2024

ENGINE NO

E7H5017911030000FA6

**CHASSIS NO** 

L1NNSGHA5RB074127

MILEAGE

: -

DATE IN

. .

**ESTIMATED BY** 

JOHNNY BOO / ALLAN WU

**ACCIDENT DATE** 

11-Nov-24

PLACE OF ACCIDENT

PUNGGOL CENTRAL (OUTSIDE PARC CENTROS)





53 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

# ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNT 3410 J.

S/N	NATURE OF JOBS	ine d	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED 1210 X 1		\$ 2,000.00	1200 🗸
3	TO RESPRAY REAR BUMPER, REAR BUMPER MID, REAR BUMPER SPOILER AND BOTH REAR WHEEL ARCH TRIMS.		\$ 4,200.00	1 <b>8</b> 09 🗸
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N	\$ 480.00	/ \
	TOTAL LABOUR CHARGES	:	\$ 7,040.00	•





53 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

# MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNT 3410 J

# **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER UPPER X nn	1 \$	773.00	
2	REAR BUMPER LOWER	1 \$	773.00	/ 🗸
3	REAR BUMPER SPOILER / (V)	1 \$	387.00	) / <b>y</b>
4	REAR BUMPER REVERSE \$ FOG LIGHT (RH)/	(U) 1 \$	248.00	, / 🗸
5	REAR WHEEL ARCH TRIM - LH / RH / ///	2 \$	350.00	) /
6	SUNDRIES	\$	500.00	)
	TOTAL SPARE PARTS	: 5	3,031.00	<del>.</del>
	TOTAL LABOUR CHARGES	: 5	7,040.00	<u>.</u>
	GRAND TOTAL	: [	10,071.00	
		_		<del></del>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE :
AUTHORISED DATE :

EXCESS COST :

REMARKS

Steve (LKK) 19/11/24, 2.30 ph UL L PIP

MACH, 4 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE

PROGRESS OF REPAIR, WE SHALL INFORM YOU

ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT SP1424BC0001 / PREMIUM AUTOMOBILES PTE LTD [408699] ENTRY DATE & TIME: 12/11/2024 18:08 (SGT) SUBMITTED BY: LIM KEE SIANG VERSION: 1 (12/11/2024 18:08 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

**Date of First Submission** 12/11/2024 18:08 (SGT) Reported by **Both Policyholder and Actual Driver Date of Accident** 11/11/2024 18:53 (SGT) **Exact Location of Accident** Singapore **Additional Location Information PUNGGOL CENTRAL (OUTSIDE PARC CENTROS)** Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SNT3410J

#### INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner SOONG CHIN KHANG NRIC No SXXXX719I **Email Address** soongchinkhang@hotmail.com Mobile Phone No (Phone) +65-97828858 Alternative Phone No

## VEHICLE PARTICULARS


Manufacturer **XPENG** Model G6 Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car **Transmission** Auto CC Vehicle Fuel **Electric** First Regisration Date Chassis no

## **INSURANCE COMPANY**

Effective Date/Time of Ownership

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 7240194396

DRIVER



Page 1 of 27



Name of Driver SOONG CHIN KHANG NRIC No SXXXX719I Date Of Birth 18/12/1979 Occupation Indoor Driving Pass Date .... 01/12/1999 **Driving License Pass Class** Driving License Validity Valid Driving experience 24 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-97828858 Alt. Phone Number Email Address soongchinkhang@hotmail.com Address 27 FERNVALE ROAD Address complement #22-27 Postcode 797415 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

## GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID .... Translator's phone number Translator's email Original language used in the statement

#### **DETAILS OF POLICE ACTION**

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

## CIRCUMSTANCES OF ACCIDENT

TRAFFIC LIGHT STOP AT PUNGGOL CENTRAL OUTSIDE PARC CENTROS.

I, DRIVER OF SNT 3410 J STOPPED AT THE RED LIGHT AND SNF 7602 U HIT MY REAR (VIDEO AS ATTACHED). IT HAPPENED ON 11/11/2024, 1853HPRS


## ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

Yes


# DETAILS OF OTHER VEHICLE PROPERTY 1



Page 2 of 27



Vehicle Registration Number	SNF7602U
Vehicle Manufacturer	
Vehicle Model	
Vehicle Variant	
Vehicle Colour	1
Vehicle Category	Private car
Name of Driver	NG GEOK CHOON
Contact Number	-
Address	
Address complement	
Postcode	
Insurance Company Name	Mary Mary 1895, 1541
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	





#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>Inuthful and accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for exchiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any refevent government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,

Policytodae | Egypture / Date & Time | 1500Hrz

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Contre Personnel (Name as in NRIC1D care)

Sketch Plan

SNT34103

-SNK 7602U

Λ

Accident report SP1424BC0001

Page 4 of 27



Traffic light stop at Punggol Central ou I, driver of SNI340J stopped at the red hit my year (video as attached). It happ	Aside Parc Centros.
I, driver of SNT3410J stopped at the red	light and suf76024
hit my hear (video as affached). If happ	sened on 11/11/2021, 18.
	A STATE OF THE STA
ration	
eclare the foregoing particulars are true in every respect.	^
	el de
11.	

Accident report SP1424BC0001

v.Jun2022

Page 5 of 27

