

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A #01-374/393, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67337719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLU 9139Y
 TP 1A1G

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Estimate No: ES2400960/WL
 Date: 18 Nov 2024
 Policy No: DMPG23016384
 Veh Reg No: SLU9139Y
 Make/Model: TOYOTA TOYOTA
 HARRIER PREMIUM 2.0
 CVT

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Chassis No: ZSU600104563
 Engine No: 3ZRB996060
 Reg. Date: 18/12/2017

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 11/11/2024
 TP Veh Reg No: SMF1195D

*Not Whairw
 6/ky &
 Repair After Rain
 4 days*

Estimate Repair Cost to Vehicle No: SLU9139Y

| Description | U/Price | Quantity | List Price | Amount |
|--|----------|-----------|------------|----------|
| | | | SS | SS |
| List Price | | | | |
| 1 REAR BUMPER | 2,236.30 | 1 PC | 2,236.30 | — |
| 2 REAR BUMPER LOWER SKIRT COVER | 649.40 | 1 PC | 649.40 | — |
| 3 REAR BUMPER CLIP | 5.50 | 6 PC | 33.00 | — |
| 4 REAR TAILGATE | 2,427.00 | 1 PC | 2,427.00 | — |
| 5 TAILGATE EMBLEM 'HARRIER' | 91.80 | 1 PC | 91.80 | — |
| 6 REAR WINDSCREEN GLASS MOULDING | 220.60 | 1 PC | 220.60 | — |
| 7 REAR SMART KEY SENSOR | 91.70 | 1 PC | 91.70 | 7 |
| | | | 5,749.80 | |
| | | Less 25%: | 1,437.45 | 4,312.35 |
| Special Net | | | | |
| 8 REAR WINDSCREEN GLASS SEALANT | 40.00 | 1 PC | 40.00 | 40.00 |
| Labour | | | | |
| 9 REMOVE AND REFIX REAR WINDSCREEN GLASS | 120.00 | 1 LA | 120.00 | ✓ |
| 10 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENTS, TO KNOCKING & REPAIR REAR PANEL & REALIGN THE SAME | 600.00 | 1 LA | 600.00 | 450 |
| 11 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, REAR PANEL & REAR AFFECTED AREAS | 700.00 | 1 LA | 700.00 | 440 |
| 12 REMOVE & REFIX REVERSE CAMERA, SENSOR & SMART KEY SENSOR & RESET SYSTEM | 50.00 | 1 LA | 50.00 | ✓ |
| | | | 1,470.00 | 1,470.00 |

Total S\$ 5,822.35
 Add GST @ 9% 524.01
Total Amount Payable S\$ 6,346.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

Acknowledged by Repairer
 Signature:
 Date:

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 12/11/2024 18:35 (SGT)
Reported by Actual Driver
Date of Accident 11/11/2024 16:52 (SGT)
Exact Location of Accident Singapore
Additional Location Information KRANJI SLIP RD TWDS WOODLANDS RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU9139Y
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner HENG HENG COMMUNITY FOUNDATIONS
Company Reg No 5XXXX229W
Email Address judyngasc@gmail.com
Mobile Phone No (Phone) +65-90047043
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model HARRIER PREMIUM 2.0 CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1986
Vehicle Fuel -
First Registration Date 18/12/2017
Chassis no ZSU600104563
Effective Date/Time of Ownership -

INSURANCE COMPANY

Name of Insurance Company ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number DMPG23016384

DRIVER

| | |
|--|----------------------|
| Name of Driver | NGA SEOK CHOO JUDY |
| NRIC No | SXXXXD25D |
| Date Of Birth | 17/03/1967 |
| Occupation | Indoor |
| Driving Pass Date | 07/11/1994 |
| Driving License Pass Class | 3 |
| Driving License Validity | Valid |
| Driving experience | 30 YEARS |
| Gender | Female |
| Mobile Number | (Phone) +65-90047043 |
| Alt. Phone Number | - |
| Email Address | judyngasc@gmail.com |
| Address | 440 FAJAR RD #05-444 |
| Address complement | - |
| Postcode | 670440 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Employee |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|--------------------------|
| Type of Accident | Collision - Head to Rear |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of Intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SMF1195D |
| Vehicle Manufacturer | - |


Describe Circumstances of the Accident

CLAIM UNDER YOUR OWN COMPENSATION POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

Claim under your Own Compensation policy. **Pls check your policy for more information.**

Claim Own Policy Claim Third party Reporting Only

Claim OD (TP) at other workshop ()



I was driving along KJE towards Woodlands Road, in front was a slip road and I stopped in front of the GIVE WAY SIGN, when I moved forward, I saw a big lorry driving very fast coming towards me, so I have to stop to avoid collision. Suddenly, SMF1195D came forward and hit hard on my rear of my vehicle and caused damaged to my car.

Declaration
 I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Handwritten Signature]
 Driver's Signature (if driver is not the policyholder) / Date & Time
 12-11-2024

[Handwritten Signature] Ekesh (M)
 14/11/24

Witnessed by Reporting Centre Personnel
 (Name as in NRICID card)

Traffic Light

Lorry coming
very fast

view block (Blind spot)

SLU 9139Y

Front
SLU 9139Y

Give
WAY
Sign

↑ ↑ ↑ ↑ ↑ ↑ ↑
↑ ↑ ↑ ↑ ↑
(Trees)

SMF 1195D

Avoid collision
stop

L
P

SMF 1195D
Back Car

Lamp
post

Not keeping
a safe
distance

2
3
5
9
6
8
/
1

Towards Wardslands Rd
Upper Bunt Traill

[Signature]
12-11-2024

