

...CLAIM SUBFOLDER...(Pending for Approval)

FIRE

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'd	Status
Main	11 Nov 2024	S\$12.00 Edit Estimates	13 Nov 2024 12:38 S\$ 12.00	13 Nov 2024 08:54		Pending for Approval

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TAN LAI HUI , ID : S8770105J , Tel: +6590277594 , Email: CONVERSESTAR14@HOTMAIL.COM		
Vehicle Reg. No.:	SDQ688D		
Claim Type:	OD / M2406542	Date of Loss :	08/11/2024 01:00 - 01:59 [85 Months and 3 Days From LTA Reg Date (Man Yr)]
		Policy/Cover Note No. :	MZD04115 (Comprehensive) Coverage: 21/06/2024 - 20/06/2025
		Excess:	S\$800.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Tan Wan Cong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561		
Driver/Customer:	TAN LAI HUI (37 / Male) , NRIC: S8770105J, Tel: +6590277594 Email: CONVERSESTAR14@HOTMAIL.COM		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/Assigned To	Note	Created On	Created By	1st Read By
No results.							

NA2 LXX

14/11/2024


0955

1st survey

- vehicle badly burnt.
- uneconomical to repair
- recommend total loss

NH

NA2@lkkauto.com



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MZD04115	Date of Loss:	08/11/2024
Vehicle Reg. No.:	SDQ688D	Driveable?	NO
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	TAN LAI HUI	Contact No:	+6590277594
Driver:	TAN LAI HUI		
Make/Model:	MINI ONE, 1.2 5 DOOR (A)	Vehicle Reg. Date:	05/10/2017
Vehicle Colour:	RED	Gen Condition:	GOOD
Engine No:	F224H537B38A12A	Chassis No:	WMWXS120102G64694
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	99		
Description of Accident/Loss	ACCIDENT INVOLVING SDQ688D CAUGHT FIRE ON 08/11/2024 @ 01:10 ALONG BLK 82 CIRCUIT ROAD DECK 4B		
Remarks:	FIRE CASE. VEHICLE TOWED TO WORKSHOP BY K. KIM HIN AUTO.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	12.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	12.00
- Excess (\$\$)	800.00
Nett Amount (\$\$)	-788.00

This claim is handled by: SANDRA KHONG YEE TENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Nov 2024)

Parts: 144 MINI ONE 1.2 5 DOOR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/SDQ688D/13/11/2024 12:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

K Kim Hin Auto Pte Ltd/SDQ688D/13/11/2024 12:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00
Sub Total (\$\$)			12.00

Estimates on Labour

There are no labour items selected.

K Kim Hin Auto Pte Ltd/SDQ688D/13/11/2024 12:38 Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

LKK Auto Co. is required to certify the Repairs to the following:

- To reserve the right to inspect
- To display a copy of the estimate to the surveyor
- Parts prices are subject to the "market" basis
- Third party surveyor's report on "no" basis
- No illegal or improper practices
- Supplementary work must be approved by the insurance company and is subject to the approval of the insurance company

Acknowledged by: [Signature]

Signature: [Signature]