

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES PREMIER AUTOMOTIVE SERVICES PL INV No. AC2500053

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

ATTN: HUA YEN

INV Date 06/01/2025

Reference CS/SMR24110258/Evp3e2

/**N**T\

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNK 2604X

Insured Veh. SMB 1387M

Claim No. BUS/11/24/7005

Policy No.

Accident Date 01/11/2024

Inspection Date 13/11/2024

Description	Total
Survey Inspection	128.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
	STRIDES PREMIE	R AUTOMOTIVE SERVICES PL		Ref:	CS/SMR24110258/Evp3e2(N)
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	06/01/2025
	ATTN: HUA YEN			Code:	SMR
1.		Policy Particulars :	- THIRD PARTY	CLAIN	1
	Insured Veh.	SMB 1387M	Veh. Inspected	l	SNK 2604X
	Policy No.		Coverage (\$)		0.00
	Claim No.	BUS/11/24/7005	Excess (\$)		0.00
	Assign From	HUA YEN	Assign Date		12/11/2024
2.		Vehicle Partic	ulars & Conditi	on	
	Make & Model	M.G. ZS EV AT DELUXE EX	c.c		0
	Engine No.	HIDDEN	Year of Reg.		2023
	Chassis No.	LSJW74095MZ115771	Colour		BLACK
	Odometer	69001 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	215/50 R17	MICHELIN		4 mm
	L/H Front Tyre	215/50 R17	MICHELIN		4 mm
	R/H Rear Tyre	215/50 R17	MICHELIN		4 mm
	L/H Rear Tyre	215/50 R17	MICHELIN		4 mm
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT O/S PORTIO	N.	
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/11/2024	Inspection Dat	е	13/11/2024
	Survey held at	WORLD AUTO PTE LTD			
		NO.5, KIM CHUAN LANE SINGAPORE 537070			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate I	Days of Repair		
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Worki	ng Days
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Worki	ing Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNK 2604X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	930.00	930.00
1	FRONT BUMPER LOWER GARNISH	CUT	720.00	720.00
1	FRONT BUMPER SIDE RETAINER R/H	BROKEN	63.00	63.00
1	FRONT FENDER - RH	DENTED	670.00	670.00
1	FRONT FENDER WHEEL ARCH MOULDING RH	CUT	330.00	330.00
1	FRONT FENDER UNDER DUST COVER - RH	NOT NECESSARY	310.00	-
1	HEADLAMP ASSY RH	CUT	1,800.00	1,800.00
1	SIDE MIRROR ASSY RH	BROKEN	1,100.00	910.00
2	SPORTS RIM @\$1730.00	CUT (1PC ONLY)	3,460.00	1,190.00
2	TPMS @\$460.00	BROKEN (1PC ONLY)	920.00	360.00
	LESS 10% DISCOUNT		-1,030.30	-697.30
			9,272.70	6,275.70
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER UNDER DUST COVER CLIPS (SN)	NOT NECESSARY	50.00	-
2	TYRE - 215/55/17 @\$180.00 (SN) (50% DEPRECIATION)	TORN (1PC ONLY)	360.00	90.00
			460.00	120.00
	<u>LABOUR</u>			
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	60.00
	COMPUTERISED ALIGNMENT.		180.00	100.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN RIGHT SIDE BODY CHASSIS PANELS WHERE NECESSARY, AND REPLACE ABOVE PARTS.		800.00	550.00
	REMOVE AND REPLACE RIGHT SIDE FRONT AND REAR SPORTS RIMS AND TYRES.		180.00	50.00
	PUTTY AND SPRAY PAINT ACCIDENT AFFECTED AREAS.		800.00	650.00
			2,140.00	1,410.00
	GRAND TOTAL		11,872.70	7,805.70

Report Ref No. CS/SMR24110258/Evp3e2(N)



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		7,805.70
-----------------------------	--	----------

Report Ref No. CS/SMR24110258/Evp3e2(N)



CHEN 130E TEE

Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator

SM0Z24B40005 / MODERN AUTOMOTIVE PTE LTD ENTRY DATE & TIME: 04/11/2024 17:38 (SGT) SUBMITTED BY: CHIN SOI SHONG GRACE VERSION: 1 (04/11/2024 17:38 (SGT))



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 04/11/2024 17:38 (SGT) Reported by **Actual Driver** Date of Accident 01/11/2024 19:50 (SGT) Exact Location of Accident Woodlands Centre Rd, Singapore Additional Location Information WOODLANDS TRAIN DROP OFF POINT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Private hire

Vehicle Registration Number SNK2604X

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner

CURRENT LEASING PTE LTD

Company Reg No 2227

Email Address

Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

Manufacturer MG Model ZS EV ΕV

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle?

Vehicle Category Private hire Transmission Auto

1966

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited

Policy Number / Cover Note Number 5133210951

DRIVER

Name of Driver	JEFFREY TAN BOON SWEE
NRIC No	
Date Of Birth Occupation	Outdoor
Driving Pass Date	Outdoor 04/05/1995
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	29 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	
Alt. Phone Number	-
Email Address	
Address	
Address complement	-
Postcode	
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?	Hirer
Vehicle Registration Number of Other Vehicle Owned by Driver	No
vehicle Negistration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any favoing valued in the assistant?	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident	No
Was anybody injured in the Accident?	2
Was any injured conveyed to hospital by ambulance?	No -
Was any other vehicle or property damaged?	- Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s)	7
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	
Original language used in the statement	-
PASSENGER 1	
Name	PASSENGER
Gender	Female
	Temale
PASSENGER 2	
Name	PASSENGER
Gender	Female
PASSENGER 3	
Name	PASSENGER
Gender	Male
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

AS PER STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

Yes

Reasons for not uploading a video of the accident WITH OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMB1387M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	MA HANG LOONG
NRIC No	
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	=
Details of property damaged in accident	=
No. Of Passenger (Including Driver)	-
- , - ,	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8: Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that;

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with-my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Pu:poses; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their Jawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



On the evening of 1st Nov 2024 near woodland strain station drop of point at around 1930 his, as I was forming on the extreme loft lane and my relicie was stationary walting pattently behind the ye now Box just beside the bus stop for my turn to proceed to the proper drop of point, a SMRT BUS (SMB 1387 M) drivers by Mr. Ma Hang Loong IIc are S825616 H recklessly cut into the lane that I was in from the lane on my right and hit and damaged my car arther right side while doing so. Despite my repeated afterpts to warm him by pressing my car horn several times, there were no aftempts by him to stop his bus immediately but instead continued to move forward and but into the bus stop. As a result of his care less and rections action, whe and my 3 pax were shocked and transactional by what happened. Besides my vehicle, as black may by what hand side.	cribe Circumstance of the Accident
	On the evening of 1st Nov 2024 Near Woodland strain station drop of point at around 1950 his, as I was forming on the extreme left lane and my relicie was stationary walting pattently behind the ye have box just beside the bus stop for my turn to proceed to the proper drop of point, a SMRT BUS (SMB 1387M) drivers by Mr. Ma Hang Loong He are \$823566 H recklessly cut into the lane that I was in from the lane on my right and hit and damaged my car anthe right side unite doing so. Despite my repeated attempts to warm him by pressing my car horn several times, there were no attempts by him to stop his bus immediately but instead continued to move forward and but into the lass stop. As a result of his care less and rections by what happened. Besides my vehicle, as black may by what happened.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time Actual Driver's Signature (if driver is not the policyholder) Witnessed by Regording Centre Personnel (Name as in NRIC/ID card)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 1 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 2 of 17)












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 3 of 17)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R **INSPECTION PHOTOS (Page 4 of 17)**











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 5 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 6 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R **INSPECTION PHOTOS (Page 7 of 17)**











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 8 of 17)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 9 of 17)














INSPECTION PHOTOS (Page 10 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 11 of 17)













INSPECTION PHOTOS (Page 12 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R **INSPECTION PHOTOS (Page 13 of 17)**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 14 of 17)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 15 of 17)












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 16 of 17)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 17 of 17)









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 9)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 2 of 9)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 3 of 9)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 4 of 9)













REINSPECTION PHOTOS (Page 5 of 9)













REINSPECTION PHOTOS (Page 6 of 9)













REINSPECTION PHOTOS (Page 7 of 9)













REINSPECTION PHOTOS (Page 8 of 9)













REINSPECTION PHOTOS (Page 9 of 9)







