



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP14924060270/Unp3e2	
BLK 1 KAKI BUKIT AVE 6		Date:	22/07/2024	
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 ON		Code:	TP149	
BEHALF OF OIE ZHEN WEN				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SKX 8391L	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	27/06/2024	
2. Vehicle Details				
Make & Model	NISSAN QASHQAI (A)		C.C	1197
Engine No.	HRA2191994A		Year of Reg.	29/12/2015
Chassis No.	SJNFEAJ11U1491664		Colour	SILVER
Odometer	153530 KM		Steering	IN ORDER
Brakes	IN ORDER		General	GOOD
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
		Size	Make	Balance (mm)
R/H Front Tyre		215/60R17	FALKEN	6
L/H Front Tyre		215/60R17	FALKEN	6
R/H Rear Tyre		215/60R17	FALKEN	6
L/H Rear Tyre		215/60R17	FALKEN	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2024		Inspection Date	27/06/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				