

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401813

INV Date : 12-12-2024

Reference CS/SMR24110268/Rvp3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SME 1109J
Insured Veh. SHD 6260K
Claim No. TAX/09/24/2038
Policy No.
Accident Date 15/09/2024
Inspection Date 27/11/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24110268/Rvp3e2
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Date:	12/12/2024
	Code:	SMR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6260K	Veh. Inspected	SME 1109J
Policy No.	-	Coverage	0
Claim No.	TAX/09/24/2038	Excess	\$0.00
Assign From	HUA YEN	Assign Date	13/11/2024

2. Vehicle Details

Make & Model	B.M.W. IX1 EDRIVE	C.C	-
Engine No.	HIDDEN	Year of Reg.	25/06/2024
Chassis No.	WBY72EG0805Z58476	Colour	WHITE
Odometer	6335 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55 R18	BRIDGESTONE	6
L/H Front Tyre	225/55 R18	BRIDGESTONE	6
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/09/2024	Inspection Date	27/11/2024
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SME 1109J

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$40.00	\$40.00
1	LH WHEEL HOUSING STRUT EXTENSION (SN)	NOT NECESSARY	\$194.65	\$0.00
1	LH SIDE SILL TRIM PANEL PRIMED (LIN (SN)	NOT NECESSARY	\$409.40	\$0.00
			\$644.05	\$40.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPLACE FRONT LEFT WHEEL ARCH, MAKE GOOD FRONT LEFT FENDER AND ATTACHMENTS	NOT NECESSARY	\$1,275.00	\$850.00
	TO RESPRAY FRONT LEFT FENDER AND AFFECTED AREAS		\$1,180.00	\$1,180.00
	TO TEST DRIVE, CHECK ELECTRICAL FOR PROPER FUNCTION		\$177.00	\$0.00
	TO CARRY OUT DIAGNOSTIC, TEST MODULES, DE-ENERGISE AND RE-ENERGISE THE HIGH VOLTAGE SYSTEM BY BMW QUALIFIED EXPERT (FOR FULL EV) (ADDITIONAL)		\$531.00	\$531.00
			\$3,163.00	\$2,561.00
GRAND TOTAL			\$3,807.05	\$2,601.00
	RECOMMENDED COST OF REPAIRS			\$2,601.00
Report Ref No: CS/SMR24110268/Rvp3e2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 71674
Date Estimated : 01/11/2024
Prepared By : Yap Mee Key

Page No. :

- ESTIMATE REPAIR FOR -
Sharon Koh Kai Ling (Xu Kailing)
97 Pasir Ris Heights
#15-25

- ACCOUNT - 49636
Smrt Taxis Pte Ltd
60 Woodlands Industrial Park E4

Singapore 757705

Singapore 519290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SME1109J	WBY72EG0805Z58476	25/06/2024	IX1 EDRIVE20 SAV	12

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To carry out diagnostic, test modules, de-energise and re-energise the high voltage system by BMW qualified expert (For Full EV)	531.00		531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
NO PARTS				

SUPPLEMENTARY ITEMS

Total Labour :	531.00
Total Parts :	

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-289

Co Reg No. 197401659W

sime
MOTORS

ST. (SIN) 03100176 Fax: 64794601



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	16/09/2024 18:39 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	15/09/2024 09:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Tampines Walk
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME1109J

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Sharon Koh Kai Ling
NRIC No	SXXXX236J
Email Address	
Mobile Phone No	
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	IX1 EDRIVE20 ALED
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	0
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD24V11070/VPC/R00/E00

DRIVER

Name of Driver	Sharon Koh Kai Ling
NRIC No	SXXXX236J
Date Of Birth	-
Occupation	Outdoor
Driving Pass Date	23/09/2008
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	16 YEARS
Gender	Female
Mobile Number	-
Alt. Phone Number	-
Email Address	-
Address	-
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer to attached

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	File with owner

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6260K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

IMPORTANT NOTICE

SKETCH PLAN

1. Please read carefully the details of the accident to open up the claims process.
2. This form must be completed by the Person(s) involved in the accident.
3. Information provided must be of highest possible quality. Any willful misrepresentation of a fact may constitute an offence under the Penal Code.
4. The Police and Insurance companies may use the information of police, police on the part of insurance and insurance companies to investigate the accident.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for the purpose of maintaining a database of the details of the report and for the use of the insurers to provide information to the insured.
7. By the last portion of this report to the insurers, you hereby authorise the drawing of this report at the police and insurance companies to be made available to the insurers.
8. Consent under the Personal Data Protection Act (PDPA)
I, the undersigned, acknowledge, agree and consent that:
(a) My insurer, my broker and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and store my personal data/personal information set out in this form and any other personal information provided by me in connection with my insurance policy (collectively the "Personal Information") and disclose and transfer such Personal Information to any person who have insured vehicle(s) involved in the accident (all known) or who have insured vehicle(s) involved in the accident and who are connected to me as the "insurers", the insurers' lawyers, law firms, the Regulatory Authority of Singapore and any other person or entity (collectively the "third parties") for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation and/or research;
(ii) investigating the accident and/or my claims;
(iii) carrying out my business with my insurers or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which may include disclosure of certain personal data) and/or to bring about delivery of the amount as well as on the external board of arbitration and/or other legal and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(vi) if I am insured by more than one insurer, the insurers' lawyers, law firms, may be permitted to use, disclose and/or transfer my Personal Information for one or more of the above purposes, and
(vii) any Personal Information may be disclosed by any of the insurers and/or GIA to their third party, to and persons to whom it is disclosed may use, disclose and/or transfer, which may be used outside of Singapore, for one or more of the above purposes.


[Signature] 16005
16/9/2008

Witnessed by: *[Signature]*

Witnessed by: *[Signature]*

Witnessed by: *[Signature]*

Sketch Plan:



Veh. A SHF 1109J

Veh. B SHD 6260K



SINGAPORE POLICE FORCE



T/20240915/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20240915/7019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2024 11:14		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: Sharon Koh Kai Ling			Address:		
ID Type / ID No.: NRIC NO /			Contact No.: Home/Office:		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age:	Date of Birth:	Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Real estate agent			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 15/09/2024 09:15	Type of Location: Straight Road
Location: TAMPINES WALK				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD6260K	Motor car	TOYOTA	PRIUS	Maroon	Slightly Damaged	1
SME1109J	Motor car	BMW	IX1 EDRIVE20 ALED	White		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
SME1109J	LIBERTY INSURANCE PTE LTD	SD24V11070	25/06/2024	24/06/2025



**SINGAPORE
POLICE FORCE**



T/20240915/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20240915/7019

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SHARON KOH KAI LING	ID No.	
Related Vehicle	SME1109J (Motor car)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

Subject: Reckless Passenger Incident at 1 Tampines Walk on 15 September (Video Footage Available)

Dear Sir/Madam,

I am writing to report an incident involving a reckless passenger alighting from a taxi, which resulted in damage to my vehicle. The incident took place on 15 September at 9:14 AM at 1 Tampines Walk, Tampines Hub.

A taxi had stopped to drop off a passenger, who opened the right-side door without checking for oncoming traffic. The door collided with my vehicle, a new BMW, causing scratches and damage. I have video footage of the incident, which I am prepared to provide as evidence.

I would like to file a formal report and seek advice on the next steps.

Thank you for your assistance. Please let me know if further information or the video footage is required.

Kind regards,
Sharon Koh
Contact: 92991220
SME1109J



**SINGAPORE
POLICE FORCE**



T/20240915/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20240915/7019

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
KASMAWATI BTE SAMIAN
Contact No.: 65476368

Signature Of Informant:
The identity of the person making this report has been
authenticated by Singpass. No signature is required.

Date/Time:
15/09/2024 11:14

Classification Of Case:

NP168

PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J



PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J



PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SME 1109J

