

(08/11/15) Wel
ASS. REC. BY:

REF:

CS/SMR24110268/Rvp3

2363

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SMR 1109J

at Workshop m/s PERFORMANCE

of ALEXANDRA RD

Insured: SHD 6260K SMR

Policy No.

Claims No. TAX/09/24/2038

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

10.30

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

206K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIM 10/K

Veh No:

SMR 1109J

Yr Regn:

2024 JUN

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W IXI EDRIVE

C.C

Colour

WHITE

A/C: Insured / Std / Nil / NA

Sp. Reading

06335

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

WBY 72EG 0805 258476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

R:

225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

ALEXANDRA

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Path to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Path to?

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

: \$ + RS \$

: Photos

: Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

Report Format:

Lump Sum / L.B.I. (\$

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

GST REG. NO : M2Signature: 020081 - X

Date:

E S T I M A T E

1 Nov 2024

Estimate No. : b1 71674
Date Estimated : 01/11/2024
Prepared By : Yap Mee Key

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Sharon Koh Kai Ling (Xu Kailing)
97 Pasir Ris Heights
#15-25

Singapore 519290

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME1109J	WBY72EG0805Z58476	25/06/2024	IX1 EDRIIVE20 SAV	12

DESCRIPTION

To replace front left wheel arch, make good front left fender and attachments.

850 1,275.00

To respray front left fender and affecte areas.

1,180.00

To test drive, check electrical for pro- per function.

177.00

Sundries.

30 40.00

Total Labour 1: 2,672.00

DESCRIPTION

LH WHEEL HOUSING STRUT EXTENSION X
LH SIDE SILL TRIM PANEL PRIMED (LIN X

QTY	PRIC	VALUE
1	194.65	194.65
1	409.40	409.40

Total Parts : 604.05

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Rep No. _____ Claim No. _____
Date & Time 27/11/24 Excess: \$S _____
Surveyor's Name Rasan _____
Surveyor's Tel 90010068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 2 days
Rasan after repair



Labour 1	:	2,672.00
Parts	:	604.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	294.84
Grand Total	:	3,570.89

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	236J
Vehicle Details	
Vehicle No.:	SME1109J
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2024
Vehicle Make:	B.M.W.
Vehicle Model:	IX1 EDRIVE20 ALED
Primary Colour:	White
Manufacturing Year:	2024
Engine No.:	-
Chassis No.:	WBY72EG0805Z58476
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$46,962.00
Original Registration Date:	25 Jun 2024
First Registration Date:	25 Jun 2024
Transfer Count:	0
Actual ARF Paid:	\$21,228.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2034
PARF Rebate Amount:	\$15,921.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2034
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$92,700.00
COE Rebate Amount:	\$88,757.00
Total Rebate Amount:	\$104,678.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 28 Nov 2024

OK

BMW iX1 Electric eDrive20

\$203,888 Instalment \$1,709/mth

PREMIUM AD

💰 Apply for 2.48% loan

♡ Shortlist

📅 Loan Calculator



Overview

Financial

Photo

Research

Depreciation	📘 \$20,580 / year
Reg. Date	19-Apr-2024 (9yrs 4mths 21days COE left)
Mileage	11,000 km
Transmission	Auto
Power	110.0 kW (147 bhp) View specs of the BMW iX1 Electric (2024)
Fuel Type	Electric
Drive Range	-
COE	📘 \$94,010
OMV	📘 \$46,962
ARF	📘 \$21,228
Dereg Value	📘 \$91,129 as of today
No. of Owners	📘 1
Type of Veh	SUV

Features

Electric motor producing 147bhp and 250nm torque. Front