

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN

Ref: CS/INC24110283/Aqh3e2(N)

Date: 24/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 5592K	Veh. Inspected	SMM 8554T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1303868-002	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	14/11/2024

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MMBSTA13AKH002196	Colour	WHITE
Odometer	95068 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	DUNLOP	6 mm
L/H Front Tyre	185/55 R15	DUNLOP	6 mm
R/H Rear Tyre	185/55 R15	DUNLOP	6 mm
L/H Rear Tyre	185/55 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2024	Inspect Date / Time	14/11/2024 (12:37 PM)
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**