

REF:

CS/INC24110283/Aqh3

ASSIGNMENT

From: _____ Date: _____

Estimate No. _____

OD / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remarks: Marsh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMM8554T Yr Regn: 2019, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Atrage C.D. 1193Colour: White A/C: Insured / Std / NI / NASp. Reading: 95068 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AKH002196Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R15R: 185/55R15

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/11/24Survey held at Chia AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	LS \$4700, 6 days (Red \$8972.09, 66%)
	COE Expiry: _____
	Estimate given during: Yes (✓) / No ()
	1st Survey: _____
	MV: _____
	PV: _____
	Nett: _____

Date/Time, File Pass to?

1) 22/01 Typist

Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Inve (\$ _____)Report Format: TP

Report Form / P.P. / P.P.