

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	SINGAPORE CIVIL	L DEFENCE FORCE (MHA05)	Ref:	CS/SCD24110290/Tqp3e2(N)		
	91 UBI AVE 4 SING	GAPORE 408827	Date:	13/02/2025		
	ATTN: SYABIL ISN	MAIL	Code	SCD		
1.		Policy Particulars	- THIRD PARTY CLA	M		
	Insured Veh.	QX 2198Y	Veh. Inspected	SKC 2018R		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	2024 - 130	Excess (\$)	0.00		
	Assign From	SYABIL ISMAIL	Assign Date	13/11/2024		
2.		Vehicle Partic	culars & Condition			
	Make & Model	TOYOTA C-HR HYBRID	c.c	1797		
	Engine No.	HIDDEN	Year of Reg.	2017		
	Chassis No.	ZYX102005845	Colour	WHITE		
	Odometer	103297 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm		
	L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm		
	R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm		
	L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE D	ETAILS.				
5.		General	Information			
	Accident Date	10/11/2024	Inspection Date	15/11/2024		
	Survey held at	KAN FOOK SING MOTOR WOR	KSHOP			
		BLK.8 JTC DEFU INDUSTRIAL (#04-29 DEFU SOUTH STREET SINGAPORE 533758				
5a.		Re	emarks			
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W				
5b.		Estimate l	Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Wor	king Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 2018R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL-GATE	BENT	1,450.30	1,450.30
1	TAIL-GATE GARNISH	CRACKED	1,225.60	1,225.60
1	REAR BUMPER TOP	DEFORMED	703.60	703.60
1	REAR BUMPER LOWER	DEFORMED	687.45	687.45
1	REAR BUMPER REINFORCEMENT	BENT	422.30	422.30
2	REAR BUMPER SIDE RETAINER @\$152.20	DEFORMED (1PC ONLY)	304.40	152.20
10	REAR BUMPER CLIP @\$5.50	NECESSARY	55.00	55.00
1	REAR WINDSCREEN MOULDING	NECESSARY	256.50	256.50
1	TAIL-GATE EMBLEM	NECESSARY	127.50	127.50
1	TAIL-GATE CHR EMBLEM	NECESSARY	98.50	98.50
	LESS 25% DISCOUNT		-1,332.79	-1,294.74
			3,998.36	3,884.21
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
1	REAR WINDSCREEN GUM (SN)	NECESSARY	80.00	60.00
			380.00	260.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		50.00	30.00
	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/ CUT, PANEL BEATING.		450.00	400.00
	SPRAY PAINTING.		550.00	450.00
	REMOVE / REFIX WINDSCREEN.		120.00	120.00
			1,170.00	1,000.00
	GRAND TOTAL		5,548.36	5,144.21

RECOMMENDED COST OF REPAIRS 5,14

Report Ref No. CS/SCD24110290/Tqp3e2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

1,500

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

12/11/2024 10:23 (SGT) Date of First Submission Both Policyholder and Actual Driver Reported by 10/11/2024 13:00 (SGT) Pate of Accident Singapore Exact Location of Accident COMPASSVALE BOW Additional Location Information

Country/State of Loss Singapore

DETAILS OF OWN VEHICLES

Vehicle Registration Number SKC2018R

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner TEE HENG ANN NRIC No SXXXX604H Email Address HENGANN82@YAHOO.COM.SG Mobile Phone No (Phone) +65-96685197 Alternative Phone No

VEHICLE PARTICULARS


Manufacturer Toyota Model C-HR HYBRID 1.8S CVT Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1797 Vehicle Fuel Petrol-Electric First Regisration Date 17/05/2017 Chassis no ... ZYX102005845 Effective Date/Time of Ownership 17/05/2017 11:05 (SGT)

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

Great Eastern General Insurance Limited V5024963

DRIVER



Name of Driver TEE HENG ANN NRIC No SXXXX604H Date Of Birth 07/09/1982 Occupation Indoor 15/06/2009 Driving Pass Date Driving License Pass Class Driving License Validity 15 YEARS AND 5 MONTHS Driving experience Male Gender (Phone) +65-96685197 Mobile Number Alt. Phone Number HENGANN82@YAHOO.COM.SG Email Address BLK 18 UPPER SERANGOON CRESCENT 08-46 SINGAPORE Address 534027 Address complement Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Weather Conditions Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID driginal language used in the statement Name WIFE Gender Female PASSENGER 2 DAUGHTER Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes Yes

DETAILS OF OTHER VEHICLE PROPERTY!

Vehicle Registration Number	- 18 H 18	QX2198Y
Vehicle Manufacturer		-
Vehicle Model		-
	9 9	
Vehicle Colour		-
Vehicle Category		Government
Name of Driver	6.0	(±)
Contact Number	a sen s	*
Address	graduate the second	-
Address complement	11. 2 - 4.46 40 - 40 19	-
Postcode	a compression of the compression	=
Insurance Company Name		:
Nature Of Damage		. *
Details of property damaged in ac		.
No. Of Passenger (Including Drive	er)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

s Signature / Date & Time

12-11-24

Driver's Signature (if driver is not the policyholder) / Date 9.38am

12-11-24

Witnessed by Reportin Centre Personnel (Name as in NRIC/ID

Sketch Plan S 0



T/20241110/7055

1 of 3

Report No. T/20241110/7055

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TR	RT OF A TRAFFIC ACCIDENT Station Diary				
Date/Time Report Made: 10/11/2024 18:11			Vide Report No.:	Station District	
Informant's Parti	culars		The state of the s		
Name of Informant: Tee Heng Ann			Address: 18 Upper serangoon crescent #18-08-46 Riversails SINGAPORE 534027		
ID Type / ID No.: NRIC NO / S8274604H			Contact No.: Home/Office:	Mobile: 96685197	
Nationality: MALAYSIAN			Email: hengann82@yahoo.com.sg		
Sex: Age: Date of Birth: Male 42 07/09/1982			Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Procurement/Purchasing manager			Driving Licence Information: Class:	Date of Expiry:	

General Information	of the Accident			
Type of Accident:	Non-Injury Government Vehicle	Drink Drive No	Date/Time of Accide 10/11/2024 13:10	ent: Type of Location: X-Junction
Location:				
SENGKANG CENT	RAL			
Weather: Sunny	ě	Road Surface: Dry	, , , , , , , , , , , , , , , , , , ,	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Worki	ng	Traffic Volume: Light
Type of Collision: Between Moving Ve	ehicles - Head To Rear			Anyone conveyed by ambulance: No

Vehicle No.	Туре	Make	Model	Color	Condition	IN LANGUE AND AND
QX2198Y	Ambulance	in a Maria Maria Para Para Para Para Para Para Para	ending A. M. A.	99101	Condition	No of Passenger
QAZ 1301	Ambulance					0
SKC2018R	Motor car	TOYOTA	C-HR	White		10
			HYBRID 1.8S			U.
•,			CVT	\		

Vehicle No.	Insurance Company	Insurance No	Effortive Det	
SKC2018R	GREAT EASTERN GENERAL INSURANCE LIMITED		17/05/2024	16/05/2025





2 of 3

Report No. T/20241110/7055

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Any Pedestrian In	volved: No	Use of Pedestrian Crossing: NA			
No. of Pedestrian	s injured. NiL	and the second second	THE PERSON NAMED IN	Section Security	A CONTRACTOR STATE OF THE STATE OF
Driver	A COMPANY OF THE PARTY OF THE P		ID No		S8274604H
Name	Tee Heng Ann		,,,,,,,		
			Conta	ct No.	96685197
Related Vehicle	SKC2018R (Motor car)		Contact 140.		
			Class	of	Class: NIL
Hospital/Clinic	NIL		Drivin Licent Expiry	g ce &	Date of Expiry: NIL
			LAPITY		
Date Treatment	NIL	Date Disch		NIL	
No. of Days grante	Degree of	Injury	NIL		

Brief Details.

My car SKC2018R was moving slowly to the front while waiting for right turn at Compassvale Bow cross junction into Sengkang Central road and suddenly there was a bang into the rear of my car from an ambulance car plate number QX2198Y. I will attach a few photo regarding the accident.





3 of 3

Report No. T/20241110/7055

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.		
Signature Of Interpreter: Not applicable	Date/Time: 10/11/2024 18:11		
Officer In Charge Of Case: TP / AEIT / CHUA SOON KEONG Contact No.: 65476030	Classification Of Case:		
ND400			





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO.: SKC 2018R









INSPECTION PHOTOS (Page 1 of 12)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 2 of 12)













INSPECTION PHOTOS (Page 3 of 12)







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 4 of 12)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 5 of 12)













INSPECTION PHOTOS (Page 6 of 12)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 7 of 12)














INSPECTION PHOTOS (Page 8 of 12)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 9 of 12)













INSPECTION PHOTOS (Page 10 of 12)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 11 of 12)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 12 of 12)









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 2 of 8)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 3 of 8)













REINSPECTION PHOTOS (Page 4 of 8)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 5 of 8)











REINSPECTION PHOTOS (Page 6 of 8)













REINSPECTION PHOTOS (Page 7 of 8)













REINSPECTION PHOTOS (Page 8 of 8)

