



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Ref: CS/AGI24110291/Evp3e2 Date: 05/12/2024 Code: AGI
---	---

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 4203E	Veh. Inspected	SMU 1580X
Policy No.	P10311321R04	Coverage	0
Claim No.	C10032774/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	13/11/2024

### 2. Vehicle Details

Make & Model	HONDA VEZEL HYBRID	C.C	1496
Engine No.	LEB5928903	Year of Reg.	22/03/2017
Chassis No.	RU31228892	Colour	SILVER
Odometer	94951 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R16	MICHELIN	6
L/H Front Tyre	215/60 R16	MICHELIN	6
R/H Rear Tyre	215/60 R16	MICHELIN	6
L/H Rear Tyre	215/60 R16	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	11/11/2024	Inspection Date	14/11/2024
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days