



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110295/Kvh3m4
75 BRAS BASAH ROAD	Date:	29/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNS 9091L	Veh. Inspected	PZ 3888J
Policy No.	-	Coverage	0
Claim No.	MT/1303378-002	Excess	\$0.00
Assign From	EILEEN	Assign Date	14/11/2024

2. Vehicle Details

Make & Model	ISUZU LT434P (A)	C.C	7790
Engine No.	6HK1695780	Year of Reg.	01/08/2017
Chassis No.	JALLT434PH7000041	Colour	MULTI COLOUR
Odometer	177597 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80R22.5	RUNEVER	9
L/H Front Tyre	295/80R22.5	RUNEVER	9
R/H Rear Tyre	295/80R22.5 (D)	ROVELO	9/9
L/H Rear Tyre	295/80R22.5 (D)	ROVELO	9/9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/11/2024	Inspection Date	15/11/2024 (15:14)
Survey held at	SERVE YOU MOTOR SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days