Serveyor:	REF: CS1/I PM24110	0303/Enh3 (SJC 2052C)	
ASSIGNMENT (Office)			Special Instruction:
From (Person): BAYUSURIA			L/SUM: \$11,350 / REPAIR: 10 WORKING DAYS
Estimated Cost:	Bill to:	Date/Time: 14/11/2024	Third Parties:
			Claimant:
OD/TP Re-inspection / Evaluar	tion		Surveyor: SL AUTO CONSULTANTS
To Inspect Vehicle No: SJC 2	052C	Insured: JPL 1251	Workshop: 168 AUTO SERVICES PTE LTD
at Workshop m/s 168 AUTO SEF		Tel:	
of 176 SIN MING DRIVE #05-1			<del></del>
Policy No:		Claim No. 22/22/22/\/D02/3	257625
Sum Insured:		Evaces:	*
Make of Vell.		D.O.A. <u>17/07/2022</u>	Company and the second
(Client's Record)		D.O.A	
		1	H.O.D. Endorsement/Date:
Date/Time:	Person Contacted:	Vehicle IN / OUT	
Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original days)  Date/Time: 19/11/24 Submit Final Fig 4600 , 7 days (Red \$ 6750 / 59 %; Original 10 days)			
Date/Time: 19/11/24 Submi	t Final Fig 4600		59 %; Original 10 days)
Date/Time Action/Instruction			
Para(1): Parts found not replaced (To highlight R or UB, LR, Etc)			
n (2)			
Para(2): Comments on consistency of damages (Parts Not Consistent: NC)			
	,		
Para(3): Nett Value			
Market Value	·	Inchested!	Fee Charged: Date:
		Inspected/ Evaluated by:	Basic & Add Transport
Salvage Value	·		Photos
Nett Value	) <b>:</b>		Others
1) Date/TimeF	le Paccio		Total
3) Date/Time F	le Pace to		•
5) Date/Time	lo Desert		- 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2
5) Date/TimeF	le Pass to	6) Date/Time	File Return to