

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CT124110314/Rvh3

3482

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

165K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR Lim 11 - 100K

Veh No:

SME3039P

Yr Regn:

2021 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA CX-82-5 ELEGANCE c.c. 2488

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

47475

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBK92WLA00305

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R19

R:

C.A.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

09/11/24

D.O.I.

22/11/24

Survey held at

TANJONG P

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Path to?

☐

: Prel. Report

☐

: Final Report

Date/Time: File Path to?

2

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



## QUOTATION

CODE: C0006  
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT  
ADDRESS: 3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

PAGE NO.: 1  
DOCUMENT NO.: 2887  
DOCUMENT DATE: 12/11/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV: Lee Yao Sheng  
CSP/OP CODE: 1  
DEPT: 17354  
WIP NO.: DS/SME3039P/2048  
REF. NO.:  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

CONTACT NO.: 6389 6111  
MODEL: CX8 2.5 AT ELEGANCE 7 SEATER  
CHASSIS NO.: JM6KG2WLA00100305  
ENGINE NO.: PY31244342  
REG NO.: SME3039P  
REGN DATE: 08/06/2021

DESCRIPTION: Body repair

| Item  | Description   | Qty. | Unit Price | Stk/Status | Gross amount | GST Code |
|-------|---|------|------------|------------|--------------|----------|
|       |   |      | SGD        |            | SGD          |          |
| NOTES | SME3039P -TP Claim -China Taiping -DOA:11.11.24                     |      |            |            | 0.00         | O        |
| SUB   | TO REMOVE & REPLACE REAR BUMPER & TAIL GATE.                        |      |            | 1584       | 2,376.00     | S        |
|       | AND ALL ACCIDENT AFFECTED AREA.                                     |      |            |            |              |          |
| SUB   | TO RESPRAY REAR BUMPER, TAILGATE & CENTER FINISHER.                 |      |            | 2268       | 3,024.00     | S        |
| SUB   | TO TRANSFER REVERSE SENSORS.  |      |            | 180        | 330.00       | S        |
| SUB   | TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. |      |            |            | 670.00       | S        |
| SUB   | TO SUPPLY SEALER ON THE WINDSCREEN GLASS.                           |      |            |            | 120.00       | S        |
| SUB   | TO TRANSFER TAILGATE MECHANISM.                                     |      |            | 304        | 792.00       | S        |
| SUB   | TO REMOVE & INSTALL REAR EXHAUST ASSY.                              |      |            | X          | 792.00       | S        |
| SUB   | TO CARRY OUT BODY CAVITY PRESERVATION.                              |      |            | 150        | 250.00       | S        |
| SUB   | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                  |      |            | 150        | 250.00       | S        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8897

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417





## QUOTATION

CODE: C0006  
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT  
ADDRESS: 3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

PAGE NO.: 2  
DOCUMENT NO.: 2887  
DOCUMENT DATE: 12/11/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: I  
WIP NO.: 17354  
REF. NO.: DS/SME3039P/2048  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

CONTACT NO.: 6389 6111  
MODEL: CX8 2.5 AT ELEGANCE 7 SEATER  
CHASSIS NO.: JM6KG2WLA00100305  
ENGINE NO.: PY31244342  
REG NO.: SME3039P  
REGN DATE: 08/06/2021

DESCRIPTION: Body repair

| Item          | Description                          | Qty.  | Unit Price | Stk/Status | Gross GST |          |
|---------------|--------------------------------------|-------|------------|------------|-----------|----------|
|               |                                      |       |            |            | amount    | Code     |
|               |                                      |       | SGD        |            | SGD       |          |
| SUB           | TO REPROGRAMME AFTER THE             |       |            |            | 250       | 300.00 S |
|               | ACCIDENT REPAIR WORKS.               |       |            |            |           |          |
| SUB           | SUNDRIES.                            |       |            |            | 20        | 50.00 S  |
| K230-50-221DB | BUMPER REAR KG <i>form</i>           | 1.00  | 1,242.88   | STOCK      | 1,242.88  | S        |
| B45A-56-146A  | FASTENER <i>ne</i>                   | 14.00 | 2.36       | STOCK      | 33.04     | S        |
| BHN1-50-0Z1A  | GROMMET, SCREW <i>ne</i>             | 4.00  | 2.36       | STOCK      | 9.44      | S        |
| B33J-51-833   | RIVET, SPLASH SHIELD <i>ne</i>       | 4.00  | 6.49       | STOCK      | 25.96     | S        |
| G001-67-061   | PAD, PROTECTOR <i>ne</i>             | 7.00  | 7.08       | NO STOCK   | 49.56     | S        |
| BGV4-56-145   | CLIP <i>ne</i>                       | 10.00 | 2.36       | STOCK      | 23.60     | S        |
| K131-50-2H1A  | RETAINER RHR BUMPER KG <i>7</i>      | 1.00  | 30.52      | STOCK      | 30.52     | S        |
| K131-51-5L0A  | REFLECTOR RHR KG <i>9.44</i>         | 1.00  | 473.52     | STOCK      | 473.52    | S        |
| DFR5-50-251   | BRACKET, BUMPER SKYACTIV <i>ne</i>   | 1.00  | 4.64       | STOCK      | 4.64      | S        |
| K131-50-260   | REINF REAR BUMPER KG <i>7</i>        | 1.00  | 600.54     | STOCK      | 600.54    | S        |
| K131-50-360   | GUARD RHR BUMPER KG <i>7</i>         | 1.00  | 40.71      | STOCK      | 40.71     | S        |
| KD47-67-UC5A2 | RETAINER KF <i>7</i>                 | 1.00  | 15.77      | STOCK      | 15.77     | S        |
| KD47-67-UC1   | 2'SENSOR, ULTRASONIC <i>X</i>        | 1.00  | 184.59     | STOCK      | 184.59    | S        |
| G001-67-061   | PAD, PROTECTOR <i>ne</i>             | 7.00  | 7.08       | STOCK      | 49.56     | S        |
| K3Y1-62-02XA  | BODY LIFT GATE KG <i>bt</i>          | 1.00  | 1,640.63   | STOCK      | 1,640.63  | S        |
| GHP9-58-867   | VALVE, ONEWAY <i>ne</i>              | 2.00  | 12.06      | STOCK      | 24.12     | S        |
| D24H-62-866   | COVER, HOLE RR LID S/ACTIV <i>ne</i> | 1.00  | 2.36       | STOCK      | 2.36      | S        |

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs."

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle"



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn No.: M90364005A

zoom-zoom

Showrooms & Service Centres

5 Ubi Close Singapore 408605

Sales Tel: 6395 8588 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



## QUOTATION

CODE: C0006  
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT  
ADDRESS: 3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

PAGE NO.: 3  
DOCUMENT NO.: 2887  
DOCUMENT DATE: 12/11/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: I  
WIP NO.: 17354  
REF. NO.: DS/SME3039P/2048  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

CONTACT NO.: 6389 6111  
MODEL: CX8 2.5 AT ELEGANCE 7 SEATER  
CHASSIS NO.: JM6KG2WLA00100305  
ENGINE NO.: PY31244342  
REG NO.: SME3039P  
REGN DATE: 08/06/2021

DESCRIPTION: Body repair

| Item          | Description         | Qty. | Unit Price | SGD | Stk/Status | Gross amount | GST Code |
|---------------|---------------------|------|------------|-----|------------|--------------|----------|
| D204-50-896A  | FASTENER            | 4.00 | 2.36       |     | STOCK      | 9.44         | S        |
| C001-50-897   | SPACER              | 2.00 | 3.97       |     | STOCK      | 7.94         | S        |
| GJ6A-50-897   | SPACER              | 3.00 | 11.13      |     | STOCK      | 33.39        | S        |
| G21E-63-938B  | PIN,STUD            | 1.00 | 10.20      |     | STOCK      | 10.20        | S        |
| C513-50-896   | FASTENER            | 4.00 | 7.42       |     | STOCK      | 29.68        | S        |
| K132-50-850BP | FINISHER,REAR KG    | 1.00 | 1,642.06   |     | STOCK      | 1,642.06     | S        |
| BHY1-51-0A6A  | CLIP                | 4.00 | 10.20      |     | STOCK      | 40.80        | S        |
| B01A-51-958   | CLIP,SPOILER        | 3.00 | 2.95       |     | STOCK      | 8.85         | S        |
| KB8A-51-SJ3   | CLIP                | 2.00 | 5.57       |     | STOCK      | 11.14        | S        |
| KB8A-51-W24A  | FASTENER            | 6.00 | 3.71       |     | STOCK      | 22.26        | S        |
| EG21-51-146   | FASTENER            | 3.00 | 5.57       |     | STOCK      | 16.71        | S        |
| BF67-51-261   | GROMMET             | 2.00 | 1.86       |     | STOCK      | 3.72         | S        |
| GB02-67-014   | CLIP                | 1.00 | 3.38       |     | STOCK      | 3.38         | S        |
| KD53-51-0B6B  | CLIP                | 2.00 | 2.36       |     | STOCK      | 4.72         | S        |
| KDY3-51-0A6C  | CLIP                | 2.00 | 10.20      |     | STOCK      | 20.40        | S        |
| K339-51-720   | ORNAMENT RR CX-8    | 1.00 | 49.56      |     | STOCK      | 49.56        | S        |
| TK78-51-731A  | MASCOT,REAR TC/KG   | 1.00 | 93.39      |     | STOCK      | 93.39        | S        |
| K341-51-771   | ORNAMENT SKYACTIV G | 1.00 | 59.43      |     | STOCK      | 59.43        | S        |
| PY2W-40-100C  | SILENCER MAIN KG    | 1.00 | 1,871.74   |     | STOCK      | 1,871.74     | S        |
| PE23-40-305   | GASKET EXHAUST KH   | 1.00 | 27.23      |     | STOCK      | 27.23        | S        |

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a maximum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurocar Pte Ltd 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 6369 3003, 88N 199103859N, GST Regn No: M190364005A

zoom-zoom

Storerooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6295 5688 Service Tel: 6295 6999

Sales Fax: 6846 1700 Service Fax: 6295 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6126

Sales Fax: 6476 7073 Service Fax: 6476 7417





## QUOTATION

CODE: C0006  
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT  
ADDRESS: 3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

PAGE NO.: 4  
DOCUMENT NO.: 2887  
DOCUMENT DATE: 12/11/2024  
POS ID: 12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV: Lee Yao Sheng  
CSP/OP CODE: I  
DEPT: 1  
WIP NO.: 17354  
REF. NO.: DS/SME3039P/2048  
DATE IN:  
EXT. WTY:  
MILEAGE: 0

CONTACT NO.: 6389 6111  
MODEL: CX8 2.5 AT ELEGANCE 7 SEATER  
CHASSIS NO.: JM6KG2WLA00100305  
ENGINE NO.: PY31244342  
REG NO.: SME3039P  
REGN DATE: 08/06/2021

DESCRIPTION: Body repair

| Item        | Description         | Qty. | Unit Price | SGD | Stk/Status | Gross amount | GST Code |
|-------------|---------------------|------|------------|-----|------------|--------------|----------|
|             |                     |      |            |     |            |              |          |
| PY8B-20-55X | CAT CONVERTER KG X  | 1.00 | 1,409.26   |     | STOCK      | 1,409.26     | S        |
| PE23-40-305 | GASKET EXHAUST KH X | 1.00 | 27.23      |     | STOCK      | 27.23        | S        |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 90010068  
6 days  
22/11/24  
Res 50 paint

|           | GST Code | Rate  | Service/Goods | GST      | Before GST        | GST                       | Total            |
|-----------|----------|-------|---------------|----------|-------------------|---------------------------|------------------|
| Parts     | O        | -     |               | -        |                   |                           |                  |
| Surcharge | S        | 9.00% | 18,807.97     | 1,692.72 | 18,807.97         | 1,692.72                  | 20,500.69        |
| Labour    |          |       |               |          | 0.00              | 0.00                      | 0.00             |
| Menus     |          |       |               |          |                   |                           |                  |
|           |          |       |               |          | <b>Amount Due</b> | <b>18,807.97 1,692.72</b> | <b>20,500.69</b> |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*\*Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE  
No.

Date:



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN:199103859N, CST Regn. No. M90364005A

**ZOOM-ZOOM**

Showrooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

Customer signature

Authorised signature

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |   |
|---------------------------------|---|
| Date of First Submission        | 11/11/2024 13:08 (SGT)                      |
| Reported by                     | Both Policyholder and Actual Driver         |
| Date of Accident                | 09/11/2024 11:00 (SGT)                      |
| Exact Location of Accident      | Singapore                                   |
| Additional Location Information | THE ENCLAVE CONDO CAR PARK 131 HOLLAND ROAD |
| Country/State of Loss           | Singapore                                   |

## DETAILS OF OWN VEHICLE

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SME3039P |
|-----------------------------|----------|

### INSURED/POLICYHOLDER

|                          |                         |
|--------------------------|-------------------------|
| Is company?              | No                      |
| Name Of Registered Owner | TAN THUAN LENG, SHERMAN |
| NRIC No                  | SXXXX348Z               |
| Email Address            | SHERMAN_TAN@HOTMAIL.COM |
| Mobile Phone No          | (Phone) +65-97885821    |
| Alternative Phone No     | -                       |

### VEHICLE PARTICULARS

|  |                           |
|--|---------------------------|
| Manufacturer   | Mazda                     |
| Model  | CX-8                      |
| Variant  | -                         |
| Exact purpose for which vehicle was being used at time of accident           | -                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category   | Private car               |
| Transmission   | Auto                      |
| CC   | 2488                      |
| Vehicle Fuel   | -                         |
| First Registration Date  | -                         |
| Chassis no   | -                         |
| Effective Date/Time of Ownership   | -                         |

### INSURANCE COMPANY

|                                   |                                      |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company         | AIG Asia Pacific Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | 7210054903-02                        |

### DRIVER



|  |                                       |
|--|---------------------------------------|
| Name of Driver   | TAN THUAN LENG, SHERMAN               |
| NRIC No  | SXXXX348Z                             |
| Date Of Birth  | 22/04/1988                            |
| Occupation   | Indoor                                |
| Driving Pass Date  | 25/06/2007                            |
| Driving License Pass Class                                   | 3                                     |
| Driving License Validity                                     | Valid                                 |
| Driving experience   | 17 YEARS AND 5 MONTHS                 |
| Gender   | Male                                  |
| Mobile Number  | (Phone) +65-97885821                  |
| Alt. Phone Number  | -                                     |
| Email Address  | SHERMAN_TAN@HOTMAIL.COM               |
| Address  | BLK 131 HOLLAND ROAD #03-02 SINGAPORE |
| Address complement   | -                                     |
| Postcode   | 278569                                |
| Is the driver the policyholder?                              | Yes                                   |
| If No, Relationship of the Driver with the Insured           | -                                     |
| Does Driver Own Other Vehicles?                              | No                                    |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                                     |
| Insurance Company of Other Vehicle Owned by Driver           | -                                     |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |   |
|--------------------|---|
| Type of Accident   | Hit and run / Vandalism / Damaged whilst parked |
| Weather Conditions | Clear   |
| Road Surface       | Dry   |

#### OTHER INFORMATION

|   |     |
|---|-----|
| Was any foreign vehicle involved in the accident?   | No  |
| Number of vehicles involved in the accident   | 2   |
| Was anybody injured in the Accident?  | No  |
| Was any injured conveyed to hospital by ambulance?  | -   |
| Was any other vehicle or property damaged?  | Yes |
| Number of Passengers (Including Driver)   | 0   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |
| Translator's name   | -   |
| Translator's ID   | -   |
| Translator's phone number   | -   |
| Translator's email  | -   |
| Original language used in the statement   | -   |

#### DETAILS OF POLICE ACTION

|   |    |
|---|----|
| Was the accident reported to the police?  | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom?                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO THE SKETCH PLAN

#### ATTACHMENT(S)

|   |     |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera?   | No  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | GBG1643C |
| Vehicle Manufacturer        | -        |

|   |                    |
|---|--------------------|
| Vehicle Model                           | -                  |
| Vehicle Variant                         | -                  |
| Vehicle Colour                          | -                  |
| Vehicle Category                        | -                  |
| Name of Driver                          | Commercial vehicle |
| Contact Number                          | -                  |
| Address                                 | -                  |
| Address complement                      | -                  |
| Postcode                                | -                  |
| Insurance Company Name                  | -                  |
| Nature Of Damage                        | -                  |
| Details of property damaged in accident | -                  |
| No. Of Passenger (Including Driver)     | -                  |



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time  
11/11/24 10:44

  
Driver's Signature (If driver is not the policyholder) / Date & Time  
11/11/24 10:44

  
Witnessed by Reporting Centre Personnel

Sketch Plan



Enclave Condo (B Carpark)

**Describe Circumstances of the Accident**

I parked my car in the condo's carpark at around 11 am to 11:30 am on 09/11/24 and went up to my condo unit.

At around 14:30 pm in the afternoon I came back to the car and noticed that my car was hit in the rear. There was a note on my wind screen to notify me that he is sorry that he hit my car and to contact him at 97237525.

I contacted the person, and after some conversation with him, he told me to claim his insurance for the accident.

**Declaration**

We declare the foregoing particulars are true in every respect.

x [Signature] 11/11/24  
10:51

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]  
Witnessed by Reporting Centre Personnel



Mazda CX-8 2.5A Luxury 7-Seater

**\$165,000** Instalment \$1,474/mth


















Overview

Financial

Photo

Research

|               |  |
|---------------|--|
| Depreciation  |  \$22,360 / year        |
| Reg. Date     | 28-Jun-2021<br>(6yrs 7mths 3days COE left)   |
| Manufactured  |  2021                 |
| Mileage       | 34,880 km (10.2k / year)   |
| Transmission  | Auto   |
| Engine Cap    | 2,488 cc   |
| Road Tax      |  \$1,786 / year       |
| Power         | 143.0 kW (191 bhp)<br>View specs of the <a href="#">Mazda CX-8 (2020-2024)</a>                           |
| Curb Weight   |  1,808 kg             |
| COE           |  \$63,002             |
| OMV           |  \$30,830             |
| ARF           |  \$35,162             |
| Dereg Value   |  \$67,901 as of today |
| No. of Owners |  2                    |

> **Back to OneMotoring**

### Enquire PARF/COE Rebate for Registered Vehicle

|  |                                  |
|--|----------------------------------|
| <b>Vehicle Owner Particulars</b>   |                                  |
| Owner ID Type:   | Singapore NRIC                   |
| Owner ID:  | 348Z                             |
| <b>Vehicle Details</b>   |                                  |
| Vehicle No.:   | SME3039P                         |
| Vehicle to be Exported:  | No                               |
| Intended Deregistration Date:  | 24 Nov 2024                      |
| Vehicle Make:  | MAZDA                            |
| Vehicle Model:   | CX-8 2.5 AT ELEGANCE 7 SEATER    |
| Primary Colour:  | Grey                             |
| Manufacturing Year:  | 2021                             |
| Engine No.:  | PY31244342                       |
| Chassis No.:   | JM6KG2WLA00100305                |
| Maximum Power Output:  | 143.0 kW (191 bhp)               |
| Open Market Value:   | \$30,089.00                      |
| Original Registration Date:  | 08 Jun 2021                      |
| First Registration Date:   | 08 Jun 2021                      |
| Transfer Count:  | 0                                |
| Actual ARF Paid:   | \$34,125.00                      |
| <b>Intended PARF Rebate Details</b>  |                                  |
| PARF Eligibility:  | Yes                              |
| PARF Eligibility Expiry Date:  | 07 Jun 2031                      |
| PARF Rebate Amount:  | \$25,593.00                      |
| <b>Intended COE Rebate Details</b>   |                                  |
| COE Expiry Date:   | 07 Jun 2031                      |
| COE Category:  | E - Open - all except motorcycle |
| COE Period(Years):   | 10                               |
| QP Paid:   | \$63,002.00                      |
| COE Rebate Amount:   | \$39,230.00                      |
| <b>Total Rebate Amount:</b>  | <b>\$64,823.00</b>               |
| <b>Message</b>   |                                  |
| You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. |                                  |

The information contained herein is correct as at 24 Nov 2024

OK