

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

MS FIRST CAPITAL INSURANCE LIMITED

16 RAFFLES QUAY

#42-01

HONG LEONG BUILDING
SINGAPORE 048581

ATTN : Motor Claim Department

Your Ref No: : **SHB2978K**

Claim Type : THIRD PARTY

Accident Date : 18.10.2024

Date : 21.10.2024

Veh Reg No : **SLT3936H**

Make / Model : **SUBARU XV 1.6I-S
AWD CVT**

Chassis No. : JTFAT35Y70K215690

Engine No. : FB16YB40569

Reg. Date : 27 Oct 2017

*Not Authorized
for
mercy
24/10/24
d/s \$1400
take 2 hrs. 1 hr. 1 hr.
2 hrs*

Estimate Repair Cost for Vehicle No. : SLT3936H

S/N Description

Quantity

Unit

Amount

LIST PRICE

SS

- 1 REAR BUMPER
- 2 REAR BUMPER TOP PROTECTOR
- 3 REAR BUMPER TOWING COVER
- 4 REAR BUMPER REINFORCEMENT
- 5 REAR BUMPER CLIPS (SET OF 10)

1	PCS	Torn	534.50	✓
2	PCS	Defect	981.00	✓
3	PCS	Torn	22.00	✓
4	PCS	Defect	250.30	✓
5	set PCS	new	42.00	✓

TOTAL PARTS :	1829.80
DISCOUNT 10% : 202	182.98
SUB TOTAL :	1646.82

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg**MS FIRST CAPITAL INSURANCE LIMITED**

16 RAFFLES QUAY

#42-01

HONG LEONG BUILDING

SINGAPORE 048581

Date : 21.10.2024

Veh Reg No : SLT3936H

Make / Model : SUBARU XV 1.6I-S
AWD CVT

Chassis No. : JTFAT35Y70K215690

Engine No. : FB16YB40569

Reg. Date : 27 Oct 2017

ATTN : Motor Claim Department

Your Ref No: : SHB2978K

Claim Type : THIRD PARTY

Accident Date : 18.10.2024

Estimate Repair Cost for Vehicle No. : SLT3936H

S/N Description

Quantity

Unit

Amount

S/N Description

Quantity

Unit

Amount

SPECIAL NETT

1 REAR BUMPER SENSOR

1

PCS

SS

300.00 X

TOTAL SPECIAL NETT :**300.00****LABOUR CHARGES**

1 SUNDRIES

2 PANEL BEATING

3 CHECK WIRING

4 SPRAY PAINT

SS

SS

17 30.00 X
650.00 200
60.00 20
500.00 400**TOTAL LABOUR :****1240.00****GRAND TOTAL :****3186.82****FOR FOCUS AUTO PTE LTD**LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AUTHORIZED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

p- 1328.80
202
1063.04
700
1763.04
202
1410: