

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh

CLAIM DEPARTMENT

DID : 66547727

FAX :

Date : 18/11/2024

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 09/11/2024

Vehicle No : SMT-5524-M

Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR FENDER LH <i>repair</i>	RESTORE	
1	REAR BUMPER <i>repair</i>	RESTORE	
	Sub Total	0.00	
	Discount 10% On Parts	(0.00)	
Special Nett Item			
1	REAR SPORTS RIM LH	RESTORE	
	Sub Total	0.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	500.00 <i>400</i>	

Date : 18/11/2024
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 09/11/2024
Vehicle No : SMT-5524-M Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RESPRAY AFFECTED PORTION	600.00	400
	Sub Total	1100.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1,100.00

Remarks:

4 days / Res after repair / p/p

SUB TOTAL
GST 9.0 % 99.00
TOTAL 1,199.00

Surveyor's name: Rasel - 4p 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 18/11/24