



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile      |   |                 |                       |  |
|--|---|-----------------|-----------------------|--|
| MS LIBERTY INSURANCE PTE LTD   |   | Ref:            | CS/LIP24110339/Kvh3m4 |  |
| ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE                          |   | Date:           | 13/12/2024            |  |
| 048583   |   | Code:           | LIP                   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                      |   |                 |                       |  |
| Insured Veh.   | SNM 3623Z   | Veh. Inspected  | FBL 7898T             |  |
| Policy No.   | -   | Coverage        | 0                     |  |
| Claim No.  | AVS24/3403  | Excess          | \$0.00                |  |
| Assign From  | CMPY  | Assign Date     | 15/11/2024            |  |
| <b>2. Vehicle Details</b>  |   |                 |                       |  |
| Make & Model   | YAMAHA SNIPER T150  | C.C             | 150                   |  |
| Engine No.   | G3E6E0229765  | Year of Reg.    | 21/03/2017            |  |
| Chassis No.  | MH3UG0740G0035520   | Colour          | MULTI COLOUR          |  |
| Odometer   | 3456 KM   | Steering        | IN ORDER              |  |
| Brakes   | IN ORDER  | General         | GOOD                  |  |
| Modification(s)  | RIMS: STANDARD ALLOY RIM  |                 |                       |  |
| <b>3. Conditions of Tyres</b>  |   |                 |                       |  |
|  | Size  | Make            | Balance (mm)          |  |
| R/H Front Tyre   | 90/80R17  | DUNLOP          | 2                     |  |
| L/H Front Tyre   |   |                 |                       |  |
| R/H Rear Tyre  | 120/70R17   | PIRELLI         | 4                     |  |
| L/H Rear Tyre  |   |                 |                       |  |
| <b>4. Description of Damages</b>                                       |   |                 |                       |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.        |   |                 |                       |  |
| DAMAGES SEE DETAILS.   |   |                 |                       |  |
| <b>5. General Information</b>  |   |                 |                       |  |
| Accident Date  | 04/11/2024  | Inspection Date | 21/11/2024            |  |
| Survey held at   | JD MOTORSPORTS PTE LTD - 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341 SINGAPORE 569537 |                 |                       |  |
| <b>5a. Remarks</b>   |   |                 |                       |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.        |   |                 |                       |  |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                       |  |
| <b>5b. Estimate Days of Repair</b>                                     |   |                 |                       |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days                     |   |                 |                       |  |