

BOX TYRES PTE LTD
8 KAKI BUKIT AVE.4
#02-40 S(417875)

Customer

Vehicle ident no.
SMK3959C

Repair order no.
R014159

Technician
AUTOBACS

Date
2.7.24

License plate no.

First reg. date

Model

Odometer reading: km/miles

Factory Japan 2023.0.2 : Toyota : Sienta : NHP170G :
except 16" Wheel

1

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-1°42'	-1°25'	+/-0°45'	-1°44'
		right	-1°32'			-1°31'
		cross	-0°10'	0°00'	+/-0°45'	-0°13'
	Toe	left	0°01'	0°06'	+/-0°09'	0°01'
		right	-0°01'			-0°01'
		total	-0°01'	0°11'	+/-0°17'	0°00'
	Geometrical driving axis		0°01'	0°00'		0°01'
Front axle	Camber	left	0°10'	-0°10'	+/-0°45'	0°11'
		right	-0°01'			-0°03'
		cross	0°11'	0°00'	+/-0°30'	0°14'
	Caster	left		4°50'	+/-0°45'	
		right				
		cross		0°00'	+/-0°30'	
	SAI	left		11°25'		
		right				
		cross		0°00'		
	Track differential angle	left				
		right				
	Toe	left	-0°03'	0°03'	+/-0°06'	0°04'
		right	0°09'			0°03'
		total	0°06'	0°06'	+/-0°11'	0°07'
	Setback			0°00'		
Max steering lock	left steer	left		-40°00'	+/-2°00'	
		right		35°00'	+/-2°00'	
	right steer	left		35°00'	+/-2°00'	
		right		-40°00'	+/-2°00'	