

ASS. REC. BY: Touff

REF: CS/TM124110363/Tup3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Sent _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Limits Vehicle: IN / OUT

Veh No: SH8489D Yr Regn: 2019, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai ioniq c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 877426 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KUMHC851 CVLH18869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davan h

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 19/11/24

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

Prepared By: _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CLB

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	15/11/2024
Vehicle Reg. No.:	SH8489D	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	14/11/2019
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	G4LEJU192186	Chassis No:	KMHC851CVLU18869
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,610.08
Miscellaneous Items	12.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,182.08
+ GST 9.00% (\$\$)	376.39
Nett Amount (\$\$)	4,558.47

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

15/11 @ 15:46
(Fri)
3

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 15 Nov 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH8489D/15/11/2024 15:46

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*481.10 FL RY
2	1		*FRT BUMPER UPPER MOULDING	20.00	0.00	nn *368.50 FLX
3	1		*FRT BUMPER SIDE BRKT LH	20.00	0.00	nn *35.00 FLX
4	10		*FRT BUMPER CLIPS	20.00	0.00	nn *22.00 FLX
5	1		*FRT FENDER LH	20.00	0.00	*588.80 FL RY
6	1		*FRT FENDER (BLUE-DRIVE) LH	20.00	0.00	*26.60 FL RL ✓
7	1		*FRT WHEEL RIM LH	20.00	0.00	*1,124.20 FL RL ✓
8	1		*FRT WHEEL CAP LH	20.00	0.00	*346.40 FL RL ✓
9	1		*FRT WHEEL TYRE LH	0.00	0.00	Xnn *216.00 F ?

F=Franchise part, L=ListItemDisc.

Sub Total (S\$) **3,208.60**

- List Item Discount on L Items (S\$) **598.52**

Total Parts (S\$) **2,610.08**

ComfortDelGro Engineering Pte Ltd/SH8489D/15/11/2024 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1497.20

1197.76

Tanpin 97495749
 w/p 19/11/24 @ 430pm
 U/S Resurvey after repair
 Tanpin e-Claims in
 2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00 ✓
Sub Total (S\$)			12.00
			12

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	800.00 380
2	SPRAY PAINTING	New	600.00 580
3	TUFF KOTE	New	40.00 nn ✓
4	WHEEL ALIGNMENT	New	120.00 80
Gross Labour Cost (S\$)			1040 1,560.00

ComfortDelGro Engineering Pte Ltd/SH8489D/15/11/2024 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2249.76

Is\$1800

2 days #

Date/Time: 15.11.2024 15:48

Page : 1

Sam: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 5961001

JC NO 305609977


OMER	REGN NO.: SH 8489D	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. 7010045	MODEL IONIQ(G3)	DATE/TIME IN 15.11.2024 12:35
LESS 383 SIN MING DRIVE	YR OF MANU. 14.11.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVLU188697	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
JUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 15.11.2024
NATURE: 3P 15.11.2024/C

/NO	LABOR CODE
00010	PB
00020	20-05

DESCRIPTION
LUMPSUM REPAIR-SH 8489D-TP
TP MERIMEN



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Signature Slip

Exit Pass

o.: SH 8489D LIMITS

Vehicle No.: SH 8489D

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard