

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19960/196R GS1 Reg. No. 19-960/196-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI24110365/Unp3e2(N)	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHC 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 08/01/2025	
	ATTN: ELAINE CH	EONG	Code	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLC 7779H	Veh. Inspected	SNT 9862Z	
	Policy No.	P10728868R02	Coverage (\$)	0.00	
	Claim No.	C10032921/EC	Excess (\$)	0.00	
	Assign From	ELAINE CHEONG	Assign Date	18/11/2024	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC	c.c	1996	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	SHHFK8790MU000687	Colour	RED	
	Odometer	64567 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/30Z R20	CONTINENTAL	6 mm	
	L/H Front Tyre	245/30Z R20	CONTINENTAL	6 mm	
	R/H Rear Tyre	245/30Z R20	CONTINENTAL	6 mm	
	L/H Rear Tyre	245/30Z R20	CONTINENTAL	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/11/2024	Inspection Date	19/11/2024	
	Survey held at	SPEEDWERKZ PTE LTD			
		1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a.	_ <del>_</del>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: