

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

IN	NCOME INSURAN				DAMAGE ASSESSMENT REPORT					
			Ref:	CS/INC24110371/Avh3m4(N)						
	'5 BRAS BASAH R NCOME CENTRES		Date:	22/01/2025						
A	ATTN: YEE PEI LI			Code:	INC					
1. Policy Particulars :- THIRD PARTY CLAIM										
Ir	nsured Veh.	SKT 7727E	Veh. Inspected	k	SJQ 6530P					
Р	Policy No.		Coverage (\$)		0.00					
C	Claim No.	MT/1304528-003	Excess (\$)		0.00					
Α	Assign From	JURAIDAH BINTE ABBAS	Assign Date		19/11/2024					
2. Vehicle Particulars & Condition										
IV	Make & Model	MITSUBISHI LANCER	c.c		1584					
E	Ingine No.	HIDDEN	Year of Reg.		2009					
С	Chassis No.	JMYSTCS3A9U005486	Colour		SILVER					
0	Odometer	177171 KM	Steering		IN ORDER					
В	Brakes	IN ORDER	Modification		SPORTS RIM					
G	General	GOOD								
3. Conditions of Tyres										
		Size	Make		Balance					
R	R/H Front Tyre	195/60R15	FALKEN		6 mm					
L	_/H Front Tyre	195/60R15	FALKEN		6 mm					
R	R/H Rear Tyre	195/60R15	FALKEN		6 mm					
L	_/H Rear Tyre	195/60R15	FALKEN		6 mm					
4. Description of Damages										
1	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.									
D	DAMAGES SEE DETAILS.									
5.	5. General Information									
Α	Accident Date	15/11/2024	Inspect Date /	Time	19/11/2024 ( 04:55 PM )					
S	Survey held at	HD PERFECT AUTOWORK PTE	LTD							
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875									
5a.										
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.									
5b.	Estimate Days of Repair									
E	STIMATED NORM	IAL PERIOD FOR REPAIR:		10 Work	ing Days					