

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bel. or Make Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP3664A Yr Regn: 2011 March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180K C.D. 1597

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 182697 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2040452A5-11756

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / QHTSU / PIR / SUMI /

TOYO / YOKO or Atlander

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 19/11/24

Survey held at N51

Des. of Damages: Fnt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MC</u>
	<u>COE Expiry : 30/11/2030</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Adcl Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

3 + R8 \$1

Photos

Others

Prepared For: _____

Signature of Surveyor: _____