Asst. Sign: REF:

ASSIGNMENT

From: Date:

Estim. Cost:

OD / TP / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at WORKSHOP m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Veh No: SLT6941Y Yr Regn: 2017, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Prius c.c 1797

Colour Brown. A/C: Insured / Std / Nil / NA

Sp.Reading 593689 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: ZVW40002 6450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

	N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Vals: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Habilead

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	19/11/24.

Survey held at Twin Cars.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes ( ) No ( )

Date/Time, File Pass to? 1) : Preli. Report : Final Report

Date/Time, File Return to? 2)

Report Format :

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp ($) : Interview ($) : Tech. Inv ($)

Survey Fee:

Transportation: $ + RS $

Photos

Others