

Workshops

205 Braddell Road Singapore 579701

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609886

Date/Time: 19.11.2024 08:36

Page : 1

am: ARC Repair OD(CLSO)1

JOB CARD Sales Order: 5961289

JC NC305610331

TOMER
MS
TOMER NO
RESS
(R)
(P)

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO:
SHA7884U

MILEAGE

MAKE:
HYUNDAI

FUEL

E.....1/2.....F

MODEL
KONA

DATE/TIME IN
17.11.2024 03:20

YR OF MANU
23.04.2024

TARGET DATE

CHASSIS CODE
KMH811VRU053347

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


ccident Date: 17.11.2024

ATURE: OD 17.11.2024 ****FIRE CASE****

/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHA7884U

LIMITS

Vehicle No.: SHA7884U

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard