

Your Ref: 24/24/24/VC05/029891

Date: 27th November 2024

Our Ref: CS1/LPC24110400/Enh3m4

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XE 891J

INSURED VEHICLE: XD 4728C

ACCIDENT DATE: 16/09/2024

We thank you for your instruction on 19/11/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XE 891J from M/s Pro-Option Services.
- b) Singapore Accident Statement of Vehicle XE 891J.
- c) Police Report of Vehicle XE 891J.
- d) Colour damaged vehicle photographs of XE 891J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XE 891J
Make & Model	: Scania P400LA4X2MSZ
Chassis Number	: YS2P4X20005392368
Year of Registration	: 2015
Engine Capacity	: 12742 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.