Surveyor:

REF: CS1/LPC24110400/Enh3 (XE 891J)

Special Instruction:

L/SUM : $21,000 / REPAIR : 9 WORKING DAYS

ASSIGNMENT (Office)

From (Person): GERALD POH of LPC Date/Time: 19/11/2024

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: _____

Surveyor: PRO-OPTION SERVICES

Workshop: SOON LEE AUTO TRADING

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: XE 891J Insured: XD 4728C

at Workshop m/s SOON LEE AUTO TRADING Tel: _____

of 2A KIAN TECK AVENUE SINGAPORE 628896

Policy No: _____ Claim No: 24/24/24/VC05/029891

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/09/2024

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle **IN / OUT**

Date/Time: _____ **Confirmed with** _____ **Final Fig** _____, ___**days (Red $**____/___**%; Original**___**days)**

Date/Time: 25/11/24 **Submit Final Fig** 13300, 6 **days (Red $** 7700 / 36 **%; Original** 9 **days)**

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____