

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24110413/Avh3m4(N)	
	75 BRAS BASAH R	OAD SINGAPORE 189557		Date:	07/02/2025	
	ATTN: EILEEN			Code:	INC	
1.	I. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLR 2343K	Veh. Inspected	k	SMM 6160J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1304096-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		20/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	SUZUKI JIMNY	c.c		1460	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JB74W107230	Colour		GREEN	
	Odometer	83496 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/75R15	YOKOHAMA		6 mm	
	L/H Front Tyre	215/75R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/75R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/75R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	13/11/2024	Inspect Date /	Time	20/12/2024 (03:34 PM)	
	Survey held at	CHIA AUTO SERVICES PTE LTI)			
		23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					