

ASS. REC. BY:

REF: CT21

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 851K

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

Yr Regn: 10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: N/A / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

S + RS. SI

: Fines

: Others

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

Ding Auto Pte Ltd  
Sin Ming Industrial Est. Sec C, Blk 10,#01-20  
575645



Insurer Reference: SNM24D205311  
Repairer Reference: 074191  
Date calculated: 20/11/2024 4:06 PM

Full Report  
Registration: GU456A  
Printed: 20/11/2024 4:07 PM

### Summary Information

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:	SNM24D205311	Date of Incident:	19/09/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

<b>Vehicle</b>			
Manufacturer:	NISSAN		
Model:	NV200 (M20)		
Sub Model:	BASE MODEL		
Model Sheet Number:	71 89 01		
Registration:	GU456A		
VIN number:	JN1YAAM20Z0001296		
Odometer:			
<b>Model Specs</b>			
HEATED DOOR MIRRORS	FULL WHEEL COVERS	PRODUCTION JAPAN	COMBI

*Not Authorized  
1/1/2024  
Repair After Painting  
3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Insurer Reference: SNM24D205311  
Repairer Reference: 074191  
Date calculated: 20/11/2024 4:06 PM

Full Report  
Registration: GU456A  
Printed: 20/11/2024 4:07 PM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

## Labour

Time Base 10 WU/h

Price = 42.00 SGD/h  
WU Price SGD

Code	Description		
NO NUMBER	JOB ALLOWANCE	5.0	21.00
UE10A1	RENEW L/F WING INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE, BUMPER MOULDINGS, WHEELHOUSE LINER, HEADLAMP AND NECESSARY ATTACHED PARTS	18.0	75.60
UA10A1)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	4.0	16.80
RE80A1)	RENEW L/HEADLAMP (REMOVED)	1.0	4.20
WH40A1	ADJUST HEADLAMPS	3.0	12.60
UH40A1)	R + R L/F DOOR TRIM	2.0	8.40
UJ10A1)	R + R LEFT MIRROR	1.0	4.20
PW10A1)	R + R LEFT FRONT WHEEL	1.0	4.20
PW10A1)	R + R L/F TYRE (WHEEL REMOVED)	2.0	8.40
PW10A1)	R + R TYRE/S AND/OR WHEEL/S	2.0	8.40

Insurer Reference: SNM24D205311  
Repairer Reference: 074191  
Date calculated: 20/11/2024 4:06 PM

Full Report  
Registration: GU456A  
Printed: 20/11/2024 4:07 PM

<b>Labour Cost</b>			
Panel / Mechanical Labour	Hrs	WU	
	3.90	39.0	163.80
<b>Total of Labour</b>			163.80

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description		WU Price SGD
	L/F WING NEW PART PAINTING		10.0
	TOWING EYE COVER NEW PART PAINT K1R		3.0

## Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	16.93
0299	TOWING EYE COVER NEW PART PAINT K1R	0.70

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		13.0	
Preparation Main Work Metal	0.70	7.0	29.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
<b>Total</b>	10 WU/h	23.0	96.60

Material Cost - Paint	Price SGD
New Part Painting	16.93
New Part Painting - Plastic K1R	0.70
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	44.73

## Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
0281	FRONT BUMPER	62022 JX00A	Original	400.00 ✓
1737	L/DOOR MIRROR	96302 JX06E	Original	280.00 ✓
0287	L/F BUMPER BRACKET	62225 BJ00A	Original	35.00 ?
7201	L/FR WHEEL	40300 JX50B	Original	280.00 ✗
7211	L/F WHEEL COVER	40315 JX00A	Original	130.00 ✓
0841	L/F WHEELHOUSE COVER	63843 JX31A	Original	100.00 ✗
0741	L/F WING	63101 JX00A	Original	350.00 ✓
0707	L/SIDE REPEATER LAMP	26160 8990A	Original	35.00 ✗
0571	LEFT HEADLAMP ASSY	26075 JX31A	Original	300.00 ✗
0299	TOWING EYE COVER	622A0 JX00A	Original	180.00 ✗

f: OEM Parts	<b>Savings</b>	0.00
n: Non-OEM Parts	<b>Subtotal</b>	2,090.00
u: Used parts	<b>Addition(+10.00%)</b>	209.00

Insurer Reference: SNM24D205311  
Repairer Reference: 074191  
Date calculated: 20/11/2024 4:06 PM

Full Report  
Registration: GU456A  
Printed: 20/11/2024 4:07 PM

<b>Total</b>	<b>2,299.00</b>
--------------	-----------------

### Final Calculation

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	2,090.00	
<b>Total Parts</b>	209.00	<b>2,299.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 39.0 WU X 42.00 SGD/h	163.80	
<b>Total of Labour</b>		<b>163.80</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 23.0 WU X 42.00 SGD/h	96.60	
Material Cost	44.73	
<b>Total Paint Including Material</b>		<b>141.33</b>
<b>Repair Cost Excludes GST</b>		<b>2,604.13</b>
GST (+9.00%)		<b>234.37</b>
<b>Repair Cost Included GST</b>		<b>2,838.50</b>

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission	21/09/2024 13:42 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	19/09/2024 21:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ANG MO KIO AVE 4 TOWARDS YISHUN (ROUNABOUT)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU456A
-----------------------------	--------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CALVIN LOW TRADING
Company Reg No	5XXXX084D
Email Address	calvinlowtrading@gmail.com
Mobile Phone No	(Phone) +65-91210111
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Nv200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1598
Vehicle Fuel	Petrol
First Registration Date	-
Chassis no	JN1YAAM20Z0001296
Effective Date/Time of Ownership	-

### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00090642302

### DRIVER

- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), w hich may be sited outside of Singapore, for one or more of the above Purposes.

**Sketch Plan**

Mayflower Primary School

Amk Ave 6

Amk Ave 5

Amk Ave 5

Amk Ave 6

A = GU 456A

B = SMH 1788H