

ASS. REC. BY:

REF:

C91 CT224110424/Kqh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GU 456A

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MS

NV 200

C.C.

1598

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

93366

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN14AA M 208-0001296

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

175 / 70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

19/12/24

D.O.A.

28/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S / R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/12 71 Sup & 13000 Corlu Used & 1304.13, 50%

Date/Time, File Pass to?

☐

: Prel. Report

1) 04/12 typica

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

), Extras

), Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

EZ Claims - TP

Lump Sum / I.B.L. (\$

1300

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk 10,#01-20
575645



Insurer Reference: SNM24D205311
Repairer Reference: 074191
Date calculated: 20/11/2024 4:06 PM

Full Report
Registration: GU456A
Printed: 20/11/2024 4:07 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:	SNM24D205311	Date of Incident:	19/09/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	NV200 (M20)
Sub Model:	BASE MODEL
Model Sheet Number:	71 89 01
Registration:	GU456A
VIN number:	JN1YAAM20Z0001296
Odometer:	

Model Specs

HEATED DOOR MIRRORS	FULL WHEEL COVERS	PRODUCTION JAPAN	COMBI
---------------------	-------------------	------------------	-------

Not Authorized
1/1/2024
Repair After Rain
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Insurer Reference: SNM24D205311
Repairer Reference: 074191
Date calculated: 20/11/2024 4:06 PM

Full Report
Registration: GU456A
Printed: 20/11/2024 4:07 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	JOB ALLOWANCE		5.0	21.00
UE10A1	RENEW L/F WING INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE, BUMPER MOULDINGS, WHEELHOUSE LINER, HEADLAMP AND NECESSARY ATTACHED PARTS		18.0	75.60
UA10A1)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		4.0	16.80
RE80A1)	RENEW L/HEADLAMP (REMOVED)		1.0	4.20
WH40A1	ADJUST HEADLAMPS		3.0	12.60
UH40A1)	R + R L/F DOOR TRIM		2.0	8.40
UJ10A1)	R + R LEFT MIRROR		1.0	4.20
PW10A1)	R + R LEFT FRONT WHEEL		1.0	4.20
PW10A1)	R + R L/F TYRE (WHEEL REMOVED)		2.0	8.40
PW10A1)	R + R TYRE/S AND/OR WHEEL/S		2.0	8.40

Insurer Reference: SNM24D205311
Repairer Reference: 074191
Date calculated: 20/11/2024 4:06 PM

Full Report
Registration: GU456A
Printed: 20/11/2024 4:07 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	3.90	39.0	163.80
Total of Labour			163.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	L/F WING NEW PART PAINTING	10.0
	TOWING EYE COVER NEW PART PAINT K1R	3.0

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	16.93
0299	TOWING EYE COVER NEW PART PAINT K1R	0.70

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		13.0	
Preparation Main Work Metal	0.70	7.0	29.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	23.0	96.60

Material Cost - Paint	Price SGD
New Part Painting	16.93
New Part Painting - Plastic K1R	0.70
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	44.73

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Part Source		Price SGD
0281	FRONT BUMPER	62022 JX00A	Original		400.00 ✓
1737	L/DOOR MIRROR	96302 JX06E	Original		280.00 ✓
0287	L/F BUMPER BRACKET	62225 BJ00A	Original		35.00 ✗
7201	L/FR WHEEL	40300 JX50B	Original		280.00 ✗
7211	L/F WHEEL COVER	40315 JX00A	Original		130.00 ✓
0841	L/F WHEELHOUSE COVER	63843 JX31A	Original		100.00 ✗
0741	L/F WING	63101 JX00A	Original		350.00 ✓
0707	L/SIDE REPEATER LAMP	26160 8990A	Original		35.00 ✗
0571	LEFT HEADLAMP ASSY	26075 JX31A	Original		300.00 ✗
0299	TOWING EYE COVER	622A0 JX00A	Original		180.00 ✗

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	2,090.00
u: Used parts	Addition(+10.00%)	209.00

Insurer Reference: SNM24D205311
Repairer Reference: 074191
Date calculated: 20/11/2024 4:06 PM

Full Report
Registration: GU456A
Printed: 20/11/2024 4:07 PM

Total	2,299.00
--------------	-----------------

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	2,090.00	
Total Parts	209.00	2,299.00
Labour Time Base 10 WU/h		
Total 39.0 WU X 42.00 SGD/h	163.80	138.60
Total of Labour		163.80
Paint Work Time Base 10 WU/h		
Labour Cost 23.0 WU X 42.00 SGD/h	96.60	
Material Cost	44.73	197.27
Total Paint Including Material		141.33
Repair Cost Excludes GST		2,604.13
GST (+9.00%)		234.37
Repair Cost Included GST		2,838.50

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.