

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS/LIP24110435/Eqh3e2	
	ONE RAFFLES QUA SINGAPORE 04858	AY #25-01 NORTH TOWER 3	Date:	12/12/2024	
	511457 W 511E 51666		Code:	LIP	
1.		Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLH 3565H	Veh. Inspected	SLA 1555L	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/2171	Excess	\$0.00	
	Assign From	CMSL	Assign Date	20/11/2024	
2. Vehicle Details					
	Make & Model	HONDA GRACE	C.C	1496	
	Engine No.	LEB6446656	Year of Reg.	29/10/2019	
	Chassis No.	GM41206632	Colour	BLACK	
	Odometer	194157 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/60 R15	ZEXTOUR	5	
			ZEXTOUR	5	
	L/H Front Tyre	185/60 R15	ZEXTOOK	3	
		185/60 R15 185/60 R15	ZEXTOUR	5	
	L/H Front Tyre				
4.	L/H Front Tyre R/H Rear Tyre	185/60 R15	ZEXTOUR ZEXTOUR	5	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15	ZEXTOUR ZEXTOUR of Damages	5	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15 <b>Description o</b> ED DAMAGES AT THE REAR O/S POR	ZEXTOUR ZEXTOUR of Damages	5	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15 <b>Description o</b> ED DAMAGES AT THE REAR O/S POR	ZEXTOUR ZEXTOUR of Damages RTION.	5	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15  Description of the Damages at the Rear O/S PORTS.	ZEXTOUR ZEXTOUR of Damages RTION.	5	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  EVEHICLE SUSTAIN	185/60 R15 185/60 R15  Description of the properties of the proper	ZEXTOUR ZEXTOUR of Damages RTION.	5 5	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAINI AGES SEE DETAILS  Accident Date	185/60 R15  185/60 R15  Description of the properties of the prope	ZEXTOUR ZEXTOUR of Damages RTION. formation Inspection Date	5 5	
5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  EVEHICLE SUSTAINE MAGES SEE DETAILS  Accident Date Survey held at	185/60 R15  185/60 R15  Description of the properties of the prope	ZEXTOUR ZEXTOUR  of Damages RTION.  formation Inspection Date  arks  JUDICE" BASIS.	5 5 21/11/2024 (14:02)	

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days