

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O km/s

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5BR90X Yr Regn: 2015, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire C.D. 2493

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 143066 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH300014648

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 235/80R18

BS / DUN / EXNOVA / GY / FR / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.A. 21/11/24

Survey held at Ryder

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rees of

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC

MV: 38K

PV: 23.4K

Nett: 14.6K

COE Expiry

Estimate given during : Yes ✓
1st Survey : No ()

655E

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

Survey Fee:

Transportation:

3 + R8 \$1

Photos

Others

Report Forward:
