



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 ATTN: CHARMAINE KONG			Ref: CS/LPC24110463/Avh3e2(N) Date: 21/04/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 169C	Veh. Inspected	SJC 6320C
	Policy No.		Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030205	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	21/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 116D	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WBA1V72080V250291	Colour	BLACK
	Odometer	121918 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	MICHELIN	6 mm
	L/H Front Tyre	225/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	225/40 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/11/2024	Inspection Date	22/11/2024
	Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	