

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT124110464/4vh3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 1/Q 3459Eat Workshop m/s Almaof 12Insured: PC 86765

Policy No. _____


Claims No. SNM24D206556

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$85/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 1.8 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C151R

Vehicle: IN / OUT

Date: _____ Person Contacted: 27A812048Veh No: YQ 3459EYr Regn: 12/04/14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NTR 88 c.c. 2999Colour: White A/C: Insured / Std / NI / NASp. Reading: 61726 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAANJR88EM 7100007Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: Green maxR: 185 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or De 1:um

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 08/11/24 D.O.I. 28/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Dep 13k.During survey to vehicle rear tyre H1 already replaced, reporting photo show rear tyre typeno 2nd hand sold13-1-25 P/P \$1100 insured Kelvin (red 1610, 59%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

TOTAL

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	151R

Vehicle Details

Vehicle No.:	YQ3459E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Nov 2024
Vehicle Make:	ISUZU
Vehicle Model:	NJR88AUE4A AMT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	4JZ1136N45
Chassis No.:	JAANJR88EM7100007
Maximum Power Output:	-
Open Market Value:	\$35,954.00
Original Registration Date:	12 Apr 2021
First Registration Date:	12 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$1,798.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	11 Apr 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$18,885.00
COE Rebate Amount:	\$12,048.00
Total Rebate Amount:	\$12,048.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 25 Nov 2024

OK



Home Used Cars Listing

All Category



Search

Save Search



Any status X 2021 X

Sort by Any Status, Date Posted (Newest)

3 Vehicles

Car Make

Car Model

Price Range

Depreciation

2021

Mileage



Isuzu NJR88A

\$94,800

Instl. \$1,313 /mth

\$14,160 /yr

05-Aug-2021

(6yrs 8mths COE left)

N.A.

2,999 cc

2 Owners

Diesel



1 single owner! View to believe! Call now for an no obligations discussion! Door step viewing possible!

Net Link Partners Pte Ltd|Posted 13-Nov-2024

Compare



Isuzu

\$91,888

Instl. \$1,273 /mth

\$13,790 /yr

26-Jul-2021

(6yrs 8mths COE left)

78,394 km

2,999 cc

1 Owner


Diesel



10 feet Isuzu NJR88 lorry with full canopy, good condition, well maintained. Loan available. Call now to enquire!

Posted 20-Oct-2024

Compare



Isuzu NJR88A

\$88,888

Instl. \$1,244 /mth

\$13,350 /yr

23-Jul-2021

(6yrs 7mths COE left)

N.A.

2,999 cc

1 Owner

Diesel



Best deal in the market! Reliable and powerful auto speed transmission. Well taken from previous owner. Ready for your business needs. Arrange to view actual car with our sales representative now!

Posted 23-Sep-2024

Compare

For old advertisements, view Expired ads

Save Search

3 Vehicles

Car Make

Car Model

Price Range

Depreciation

2021

Mileage

Prev

Next

20

results/page

Contact Us

Careers

Follow Sgcarmart.com

Compare

ESTIMATE

Our Ref: C20240103/TP-CHINATAIPING

Date of Survey: 28/11/2024

Vehicle.: YQ3459E ISUZU NJR88AUE4A AMT

Date Of Loss: 8/11/2024

Chassis no. JAANJR88EM7100007

Surveyor: LKK

S/N	Qty	Description	Rate	Amount \$
<u>Parts</u>				
1	1	Deck Door LH	R 500.00	X
2	2	Deck Door LH hinges	80.00 1 160.00	X
3	1	Rear mud guard LH	su 140.00	X
Sub-Total			800.00	
Less 20%			(160.00)	
Total Parts			960.00	
<u>Special Nett</u>				
4	1	Side protector frame LH	Surf 550.00	500 X
5	1	Metal rim L/R	200.00	X
6	1	Tyre L/R	240.00	X
Total Nett			550.00	
<u>Labour charges</u>				
5		Panel beating	600.00	300
6		Respray affected area	600.00	300
Total Labour			1,200.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 2,710.00

Not Authorized
LKK
Survey
28/11/24
LKK
p/p \$1100
2 hrs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the surveyor
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: