Surveyor:

REF: CS1/SCD24110466/Enp3(N)

Special Instruction:

L/SUM : 18100 / REPAIR: 9 DAYS

*Third Parties:*

Claimant:

Surveyor: ST APPRAISAL SERVICES

Workshop: HUAT HOCK MOTOR WORKSHOP

## ASSIGNMENT (Office)

From (Person): SYABIL ISMAIL of SCD Date/Time: 21/11/2024

Estimated Cost: Bill to:

**OD/TP Re-inspection / Evaluation**

To Inspect Vehicle No: SMC 2842D Insured: QX 1593X

at Workshop m/s HUAT HOCK MOTOR WORKSHOP Tel:

of BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978

Policy No: 6000190651 Claim No: 2024 - 120

Sum Insured: Excess:

Make of Veh: D.O.A. 12/10/2024

**(Client's Record)**

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

**Date/Time:** **Confirmed with** **Final Fig** , days (Red $ / %; Original days)

**Date/Time:** 25/02/25 **Submit Final Fig** 8600 , 6 days (Red $ 9500 / 52 %; Original 9 days)

| Date/Time | Action/Instruction |
|---|---|
| | |

**Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)**

**Para(3) : Nett Value**

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

| *Fee Charged:* | *Date:* |
|---|---|
| Basic & Add | |
| Transport | |
| Photos | |
| Others | |
| Total | |

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to